





CSB 3106
A1 OF A3



COUNTY OF LOS ANGELES DEPARTMENT OF COUNTY ENGINEER JOHN A LAMBIE COUNTY ENGINEER	PHOTO RECONNAISSANCE MAP OF THE SAN ANDREAS FAULT ZONE	COUNTY SURVEYOR'S MAP NO. B-3106	REVISION
	--- Recently active breaks, dashed where inferred. After D.C. Ross (1969) Zone of faulting as interpreted from aerial photographs. By Engineering Geology Section R. Waldbaum *SUBJECT TO REVISION	FILED 19 DEPUTY	

COUNTY SURVEYOR'S MAP NO. B-3106

CSB 3106

COUNTY SURVEYOR'S MAP NO. B-3106

A2 OF A2