

Devil's Gate Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 01/02/2019 1:47 PM

Project Name

Devil's Gate Reservoir Restoration Project - 2018-047.00

Date

Jan 2, 2019

Monitor Name

Carley Lancaster

Are Additional Monitors Present?

Yes

List Additional Monitors Present

Jerry Aguirre, Torrey Rotellini, Caroline Nalezny, Todd Chapman

Start Time

07:00

Start Temperature

38

Start Cloud Cover

0

Start Wind Speed

0-2

End Time

13:30

End Temperature

61

End Cloud Cover

0

End Wind Speed

0-2

Construction Activity and Personnel

Nature's Image crew used hand tools to remove weedy vegetation. Crew consisted of 19 laborers and one foreman (Ron Crawford).

What type of monitoring is being conducted?

Restoration Monitoring

Was ESA swept prior to start of work?

Yes

Covered Species Observed?

No

Which Species were observed?

N/A

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Other Wildlife Species Observed

CASJ, YRWA, AMCR, SPTO, CALT, BEWR, ACWO, MODO, WCSP, BUSH, EUST, HOFI, SOSP, RSHA, RCKI

Topics to Cover on the Next Monitoring Day

Areas of focus. Eucalyptus tree removal.

Log Entry #1

0645, conducted pre-removal sweep.

Log Entry #1 - Photos taken?

Yes

Log Entry #1 Photo A



Log Entry #1 Photo B



Log Entry #2

0700, Nature's Image crew removed weedy vegetation consisting mostly of LEPLAT and disposed of it at onsite dumpster.

Log Entry #2 - Were Photos taken?

Yes

Log Entry #2 Photo A



Log Entry #3

0930, met with LACDPW. Discussed work and disc golf coordination.

Log Entry #3 - Were Photos taken?

No

Log Entry #4

1330, conducted final sweep. Crew done removing material and will only be conducting cleanup for remainder of day.

Log Entry #4 - Were Photos taken?

Yes

Log Entry #4 Photo A



Survey Completed?

Yes

Signature

Handwritten signature in black ink.

Devil's Gate Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 01/02/2019 3:54 PM

Project Name

Devil's Gate Reservoir Restoration Project - 2018-047.009

Date

Jan 2, 2019

Monitor Name

Torrey Rotellini

Are Additional Monitors Present?

Yes

List Additional Monitors Present

Caroline Nalezny, Jerry Aguirre, Todd chapman

Start Time

07:19

Start Temperature

40

Start Cloud Cover

0

Start Wind Speed

1-3

End Time

03:00

End Temperature

59

End Cloud Cover

0

End Wind Speed

1-3

Construction Activity and Personnel

Construction monitoring, vegetation removal. Excavator, front loader ground laborers.

What type of monitoring is being conducted?

Construction Monitoring

Was ESA swept prior to start of work?

Yes

Covered Species Observed?

No

Which Species were observed?

N/A

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Other Wildlife Species Observed

CORA RSHA ANHU field mouse, wood rat, alligator lizard

Topics to Cover on the Next Monitoring Day

N/A

Log Entry #1

0710, participated in tailboard. 0715 began vegetation removal, 1045 witness RSHA predate lizard by excavator.1200 lunch

Log Entry #1 - Photos taken?

Yes

Log Entry #1 Photo A



Log Entry #1 Photo B



Log Entry #2

1230 back to veg removal 1445, finished for day. Bio left site at 1500

Log Entry #2 - Were Photos taken?

Yes

Log Entry #2 Photo A



Survey Completed?

Yes

Signature

Devil's Gate Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 01/02/2019 2:50 PM

Project Name

Devil's Gate Reservoir Restoration Project - 2018-047.009

Date

Jan 2, 2019

Monitor Name

Jerry Aguirre

Are Additional Monitors Present?

Yes

List Additional Monitors Present

Caroline Nalezny, Carley Lancaster, Torrey Rotellini, Todd Chapman

Start Time

06:55

Start Temperature

34

Start Cloud Cover

0

Start Wind Speed

1-3

End Time

14:49

End Temperature

66

End Cloud Cover

0

End Wind Speed

1-3

Construction Activity and Personnel

Monitored 1 excavator operated by Ray and 1 rock/dump truck.

What type of monitoring is being conducted?

Construction Monitoring

Was ESA swept prior to start of work?

Yes

Covered Species Observed?

No

Which Species were observed?

N/A

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Other Wildlife Species Observed

Woodrat, RTHA, CORA, HOFI

Topics to Cover on the Next Monitoring Day

N/A

Log Entry #1

0700: monitored vegetation spoils loading into dump truck. 1 excavator and 1 dump truck. All work within ESA. No fatalities. 1 Woodrat safely flushed.

Log Entry #1 - Photos taken?

Yes

Log Entry #1 Photo A



Log Entry #2

1030- monitored loading of vegetation spoils into dump truck. 3 wood rats safely flushed. 1 Woodrat mortality. All work within ESA. Working northward.

Log Entry #2 - Were Photos taken?

Yes

Log Entry #2 Photo A



Log Entry #3

1230- monitored ray loading vegetation spoils into dump truck. All work within ESA. Relocated 1 lizard, 1 western toad, 1 Woodrat and safely flushed two Woodrats and two cottontail rabbits. No mortalities.

Log Entry #3 - Were Photos taken?

Yes

Log Entry #3 Photo A



Survey Completed?

Yes

Signature

A handwritten signature in black ink, consisting of several overlapping loops and a long horizontal stroke at the end.

Devil's Gate Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 01/02/2019 12:28 PM

Project Name

Devil's Gate Reservoir Restoration Project - 2018-047.009

Date

Jan 2, 2019

Monitor Name

Todd Chapman

Are Additional Monitors Present?

Yes

List Additional Monitors Present

Carley Lancaster, Jerry Aguirre, Caroline Nalezny, Torrey Rotellini

Start Time

07:00

Start Temperature

32

Start Cloud Cover

0

Start Wind Speed

0-1

End Time

12:00

End Temperature

57

End Cloud Cover

0

End Wind Speed

1-3

Construction Activity and Personnel

working with kerry and front loader crew, grooming sediment an removing remaining large woody debris. making piles

What type of monitoring is being conducted?

Construction Monitoring

Was ESA swept prior to start of work?

Yes

Covered Species Observed?

No

Which Species were observed?

N/A

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Other Wildlife Species Observed

Black phoebe

Topics to Cover on the Next Monitoring Day

N/A

Log Entry #1

0700 monitoring front loader

Log Entry #1 - Photos taken?

Yes

Log Entry #1 Photo A



Log Entry #1 Photo B



Log Entry #1 Photo C



Survey Completed?

Yes

Signature

TAK

Devil's Gate Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 01/02/2019 5:30 PM

Project Name

Devil's Gate Reservoir Restoration Project - 2018-047.009

Date

Jan 2, 2019

Monitor Name

Caroline Nalezny

Are Additional Monitors Present?

Yes

List Additional Monitors Present

Torrey Rotellini, Jerry Aguirre, Todd Chapman

Start Time

07:00

Start Temperature

38

Start Cloud Cover

0

Start Wind Speed

0-3

End Time

15:00

End Temperature

61

End Cloud Cover

0

End Wind Speed

1-3

Construction Activity and Personnel

Scott on excavator, Ray on excavator, 3rd operator on dump truck.

What type of monitoring is being conducted?

Construction Monitoring

Was ESA swept prior to start of work?

Yes

Covered Species Observed?

No

Which Species were observed?

N/A

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Other Wildlife Species Observed

CORA, BLPH, SOSPO, WCSP, HOFI, COHA, RSHA, woodrat, CALT, BUSH, EUST, western toad

Topics to Cover on the Next Monitoring Day

N/A

Log Entry #1

0710: Tailgate meeting. 0745: Monitored vegetation removal by Scott, woodrat flushed from pile, small oak removed.

Log Entry #1 - Photos taken?

Yes

Log Entry #1 Photo A



Log Entry #2

0930: Monitoring Scott doing vegetation removal. Flushed cottontail. 1045: Multiple instances of RSHA predateding lizards near excavator.

Log Entry #2 - Were Photos taken?

Yes

Log Entry #2 Photo A



Log Entry #3

1115: Monitored Ray loading piles of vegetation into dump truck. 3 woodrats flushed. 1200-1230 lunch break.

Log Entry #3 - Were Photos taken?

No

Log Entry #4

1245: Relocated 2 western toads, 1 woodrat. Monitored Scott and Ray on excavators. 1445: Finished for the day. 1500: Left site.

Log Entry #4 - Were Photos taken?

Yes

Log Entry #4 Photo A



Survey Completed?

Yes

Signature

Carla Nalzy

Devil's Gate Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 01/03/2019 4:08 PM

Project Name

Devil's Gate Reservoir Restoration Project - 2018-047.009

Date

Jan 3, 2019

Monitor Name

Torrey Rotellini

Are Additional Monitors Present?

Yes

List Additional Monitors Present

Caroline Nalezny

Start Time

06:58

Start Temperature

43

Start Cloud Cover

0

Start Wind Speed

1-3

End Time

14:00

End Temperature

64

End Cloud Cover

0

End Wind Speed

1-3

Construction Activity and Personnel

Restoration, 19 laborers with hand tools

What type of monitoring is being conducted?

Restoration Monitoring

Was ESA swept prior to start of work?

Yes

Covered Species Observed?

No

Which Species were observed?

N/A

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Other Wildlife Species Observed

RCKI, CORA, field mouse, wood rat, CASJ, CALT, BLPH

Topics to Cover on the Next Monitoring Day

N/A

Log Entry #1

0700, participated in tailboard with nature's image. Swept area to have non-native removal take place. No areas of special concern noted. 1100 lunch

Log Entry #1 - Photos taken?

Yes

Log Entry #1 Photo A



Log Entry #2

Resumed work at 1200, crew tarping and throwing away what was pulled this morning. Conducted final sweep of area at 1345, biologist left site at 1400.

Log Entry #2 - Were Photos taken?

Yes

Log Entry #2 Photo A



Log Entry #2 Photo B



Survey Completed?

Yes

Signature

My R. M. II

Devil's Gate Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 01/03/2019 1:31 PM

Project Name

Devil's Gate Reservoir Restoration Project - 2018-047.009

Date

Jan 3, 2019

Monitor Name

Taylor Dee

Are Additional Monitors Present?

No

List Additional Monitors Present

N/A

Start Time

07:10

Start Temperature

43

Start Cloud Cover

0

Start Wind Speed

0-2

End Time

13:32

End Temperature

64

End Cloud Cover

0

End Wind Speed

0-1

Construction Activity and Personnel

Griffith crew removing remaining vegetation and debris piles, and loading into haul truck.

What type of monitoring is being conducted?

Construction Monitoring

Was ESA swept prior to start of work?

Yes

Covered Species Observed?

No

Which Species were observed?

N/A

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Other Wildlife Species Observed

AMCR, CAQU, woodrat, WREN, CALT, parrot sp., WCSP, CSJA, SAPH, RTHA, CAKI, ANHU, CORA, NUWO, NOFL, BLPH, SOSP, YRWA, mouse

Topics to Cover on the Next Monitoring Day

n/a

Log Entry #1

0700 tailgate safety meeting. 2 new crew to train. Gave environmental weap training to Jesus and Hector (#64 & 68).

Log Entry #1 - Photos taken?

No

Log Entry #2

0710 monitoring excavator remove vegetation and debris piles in northern portion.

Log Entry #2 - Were Photos taken?

No

Log Entry #3

0750 observed woodrat carcass. Appears to be from previous day.

Log Entry #3 - Were Photos taken?

No

Log Entry #4

1000 monitored excavator loading stump and wood piles throughout the site.

Log Entry #4 - Were Photos taken?

No

Log Entry #5

1140 used excavator to remove trash in project site near drain and culvert. Carry, Griffith foreman said they were going to finish with trash removal then load the telephone pole logs laying in the projrcy site then continue removing hand collected wood piles. Same work would continue tomorrow. Wood chipper is not expected until Monday depending on rain and if they can work.

Log Entry #5 - Were Photos taken?

Yes

Log Entry #5 Photo A



Log Entry #6

1315 Spoke to Carry. He said they only had hand collected piles of wood to load. I informed him that a bio monitor was no longer needed if that was the case. He confirmed they would be doing the same tomorrow; no new crew and no vegetation removal is expected. The wood chipper will be back first day of work next week. I let him know we will have a monitor onsite when the woodchipper is present. I also let him know we won't have a monitor tomorrow but he should call Lauren if anything changes.

Log Entry #6 - Were Photos taken?

No

Log Entry #10

Relocated 1 woodrat and 1 mouse.

Log Entry #10 - Were Photos taken?

No

Survey Completed?

Yes

Signature

A handwritten signature in black ink, appearing to be 'M. H. Co.' or similar, written in a cursive style.

Devil's Gate Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 01/09/2019 7:55 AM

Project Name

Devil's Gate Reservoir Restoration Project - 2018-047.009

Date

Jan 4, 2019

Monitor Name

Torrey Rotellini

Are Additional Monitors Present?

No

List Additional Monitors Present

N/A

Start Time

07:13

Start Temperature

46

Start Cloud Cover

0

Start Wind Speed

3-5

End Time

14:00

End Temperature

62

End Cloud Cover

0

End Wind Speed

3-5

Construction Activity and Personnel

Non-native removal, 19 laborers with hand tools

What type of monitoring is being conducted?

Restoration Monitoring

Was ESA swept prior to start of work?

Yes

Covered Species Observed?

No

Which Species were observed?

N/A

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Other Wildlife Species Observed

RSHA, HOFI

Topics to Cover on the Next Monitoring Day

Log Entry #1

0713, participated in tailboard. Crew clearing non-natives near ESA fence area east of DG 5. Crew will continue moving north along fence, will be clearing area near DG 5 area and along the western boundary Monday.

Log Entry #1 - Photos taken?

Yes

Log Entry #1 Photo A



Log Entry #2

1200 back from lunch, crew bagging what was pulled this morning. Biologist left site at 2:00.

Log Entry #2 - Were Photos taken?

Yes

Log Entry #2 Photo A



Survey Completed?

Yes

Signature

A handwritten signature in black ink, consisting of two parts: a stylized first name that appears to be 'Judy' and a last name that appears to be 'M'. The signature is written in a cursive, flowing style.

Devil's Gate Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 01/22/2019 7:32 AM

Project Name

Devil's Gate Reservoir Restoration Project - 2018-047.009

Date

Jan 8, 2019

Monitor Name

Carley Lancaster

Are Additional Monitors Present?

Yes

List Additional Monitors Present

Lauren Simpson

Start Time

07:00

Start Temperature

51

Start Cloud Cover

90

Start Wind Speed

0-3

End Time

13:15

End Temperature

66

End Cloud Cover

90

End Wind Speed

0-3

Construction Activity and Personnel

Nature's Image crew used hand tools to remove weedy plant material. Crew consisted of 19 workers and one foreman (Ron Crawford).

What type of monitoring is being conducted?

Restoration Monitoring

Was ESA swept prior to start of work?

Yes

Covered Species Observed?

No

Which Species were observed?

N/A

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Other Wildlife Species Observed

ACWO, CASJ, NOMO, MODO, CALT, SPTO, RSHA, ANHU, BEWR, WCSP, YRWA, EUST, RCKI

Topics to Cover on the Next Monitoring Day

Cleanup.

Log Entry #1

0700 Conducted pre-removal sweep.

Log Entry #1 - Photos taken?

Yes

Log Entry #1 Photo A



Log Entry #2

0715, Nature's Image crew removed weedy plant material from DG-4 and DG-4A. All removed material was disposed of at onsite dumpster.

Log Entry #2 - Were Photos taken?

Yes

Log Entry #2 Photo A



Log Entry #3

1315 Conducted final sweep. Crew done removing for day.

Log Entry #3 - Were Photos taken?

Yes

Log Entry #3 Photo A



Survey Completed?

Yes

Signature

A handwritten signature in black ink, consisting of several loops and a long horizontal stroke extending to the right.

Devil's Gate Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 01/08/2019 8:30 AM

Project Name

Devil's Gate Reservoir Restoration Project - 2018-047.009

Date

Jan 8, 2019

Monitor Name

Lauren Simpson

Are Additional Monitors Present?

No

List Additional Monitors Present

N/A

Start Time

06:55

Start Temperature

52

Start Cloud Cover

80

Start Wind Speed

0-3

End Time

08:35

End Temperature

58

End Cloud Cover

80

End Wind Speed

0-3

Construction Activity and Personnel

JV crew, chipper operation and loading haul trucks

What type of monitoring is being conducted?

Construction Monitoring

Was ESA swept prior to start of work?

Yes

Covered Species Observed?

No

Which Species were observed?

N/A

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Other Wildlife Species Observed

RTHA, AMCR, RCKI, CALT, CASJ

Topics to Cover on the Next Monitoring Day

Chipper returning Thursday

Log Entry #1

0700 tailboard 0745 trained 10 new JV workers (WEEP). 0830 notified that chipper would not return until Thursday. Only hauling of chipping will occur today. 0835 left project site


Log Entry #1 - Photos taken?

No

Survey Completed?

Yes

Signature

A handwritten signature in black ink, consisting of several loops and a trailing horizontal stroke.

Devil's Gate Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 01/09/2019 3:00 PM

Project Name

Devil's Gate Reservoir Restoration Project - 2018-047.009

Date

Jan 9, 2019

Monitor Name

Torrey Rotellini

Are Additional Monitors Present?

No

List Additional Monitors Present

N/A

Start Time

07:05

Start Temperature

48

Start Cloud Cover

0

Start Wind Speed

0

End Time

15:00

End Temperature

66

End Cloud Cover

0

End Wind Speed

0

Construction Activity and Personnel

20 laborers, hand tools

What type of monitoring is being conducted?

Restoration Monitoring

Was ESA swept prior to start of work?

Yes

Covered Species Observed?

No

Which Species were observed?

N/A

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Other Wildlife Species Observed

RSHA, BUSH, alligator lizard, CORA, RTHA, CASJ

Topics to Cover on the Next Monitoring Day

N/A

Log Entry #1

0704 crew tailboard. Clearing vegetation from area north of DG5. 0837, crew holding safety meeting with Haydee.

Log Entry #1 - Photos taken?

Yes

Log Entry #1 Photo A



Log Entry #2

1100 lunch, back to pulling non native around 1200. Crew done pulling veg 1330, finished bagging at 1445. 1445 conducted final sweep of area. Biologist left site at 3:00.

Log Entry #2 - Were Photos taken?

Yes

Log Entry #2 Photo A



Log Entry #2 Photo B



Survey Completed?

Yes

Signature

Jay R. AM

Devil's Gate Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 01/10/2019 2:10 PM

Project Name

Devil's Gate Reservoir Restoration Project - 2018-047.009

Date

Jan 10, 2019

Monitor Name

Torrey Rotellini

Are Additional Monitors Present?

No

List Additional Monitors Present

N/A

Start Time

07:04

Start Temperature

48

Start Cloud Cover

0

Start Wind Speed

1-3

End Time

14:07

End Temperature

62

End Cloud Cover

5

End Wind Speed

1-3

Construction Activity and Personnel

Restoration/Invasive removal. 19 laborors with hand tools.

What type of monitoring is being conducted?

Restoration Monitoring

Was ESA swept prior to start of work?

Yes

Covered Species Observed?

No

Which Species were observed?

N/A

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Other Wildlife Species Observed

AMKE, BLPH, Western Toad

Topics to Cover on the Next Monitoring Day

N/A

Log Entry #1

0705, arrived on site. Discussed plan in regards to herbicide spraying, Weather.gov stating 30% chance of rain so no spraying today. Will check on Monday but chance of rain nearly all next week.

Log Entry #1 - Photos taken?

Yes

Log Entry #1 Photo A



Log Entry #2

1200 back from lunch, continuing non-native clearing. 1345 conducted sweep of area, crew still bagging out cleared vegetation into dumpster. No areas of special concern. 1407 biologist left site.

Log Entry #2 - Were Photos taken?

Yes

Log Entry #2 Photo A



Log Entry #2 Photo B



Survey Completed?

Yes

Signature

A handwritten signature in black ink, consisting of stylized letters and a long horizontal line extending to the right.

Devil's Gate Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 01/10/2019 3:17 PM

Project Name

Devil's Gate Reservoir Restoration Project - 2018-047.009

Date

Jan 10, 2019

Monitor Name

Taylor Dee

Are Additional Monitors Present?

No

List Additional Monitors Present

N/A

Start Time

07:00

Start Temperature

46

Start Cloud Cover

0

Start Wind Speed

0-1

End Time

15:00

End Temperature

64

End Cloud Cover

10

End Wind Speed

2-4

Construction Activity and Personnel

oak tree removal, wood chipping. JV Land Clearing crew: Cary, Rick (woodchipper and excavator operator), 4 laborers (Alexis, Jesus, Albert?, Hector). 1 loader loading haul trucks. Josh operating dozer congregating hand-piled wood piles. Cary operating 1 dozer to grade road and push wood piles further from chipped piles.

What type of monitoring is being conducted?

Construction Monitoring

Was ESA swept prior to start of work?

Yes

Covered Species Observed?

No

Which Species were observed?

N/A

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Other Wildlife Species Observed

CALT, SPTO, BUSH, AMCR, COHA, RTHA, YRWA, CATH, ACWO, CORA, SOSP, RCKI, RSHA, MALL, EUST, southern alligator lizard, deer mouse, woodrat, western, side-blotched lizard, BEWR, BLPH, western fence lizard,

Topics to Cover on the Next Monitoring Day

N/A

Log Entry #1

0650 Griffith foreman confirmed that they need to remove an oak tree in southwestern portion. He said it was tagged as 66. I informed him that I was aware of the tree and would check to make sure it could be removed. He said Cary would let me know when it will be removed today.

Log Entry #1 - Photos taken?

No

Log Entry #2

0700 Tailboard meeting. Cary will come get me when he is ready to remove the oak tree.

Log Entry #2 - Were Photos taken?

No

Log Entry #3

0710 Rick started preparing woodchipper.

Log Entry #3 - Were Photos taken?

No

Log Entry #4

0736 woodchipper and excavator, operated by Rick, moved on to the project site. 0750 began loading chipper and chipping. 3 Woodrats flushed. Relocated: 1 deer mouse, 1 Southern alligator lizard, 1 western, side-blotched lizard, 2 woodrat mortalities: 1 woodrat

Log Entry #4 - Were Photos taken?

No

Log Entry #5

1305 Spoke with Cary. Woodchipper is scheduled for tomorrow. A monitor will be present.

Log Entry #5 - Were Photos taken?

No

Log Entry #6

1354 observed old alligator lizard carcass. Likely result of crushing/runover.

Log Entry #6 - Were Photos taken?

No

Log Entry #7

1400 Monitored Cary operate dozer to remove oak tree #66.

Log Entry #7 - Were Photos taken?

Yes

Log Entry #7 Photo A



Log Entry #7 Photo B



Log Entry #7 Photo C



Log Entry #8

1424 Began monitoring Rick operate excavator to load woodchipper. relocated: 1 western fence lizard

Log Entry #8 - Were Photos taken?

Yes

Log Entry #8 Photo A



Log Entry #9

1445 Cary said they were done for the day. They will continue tomorrow.

Log Entry #9 - Were Photos taken?

No

Survey Completed?

Yes

Signature

A handwritten signature in black ink, consisting of several overlapping, stylized strokes that are difficult to decipher as specific letters.

Devil's Gate Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 01/11/2019 2:05 PM

Project Name

Devil's Gate Reservoir Restoration Project - 2018-047.009

Date

Jan 11, 2019

Monitor Name

Torrey Rotellini

Are Additional Monitors Present?

No

List Additional Monitors Present

N/A

Start Time

07:24

Start Temperature

47

Start Cloud Cover

35

Start Wind Speed

1-3

End Time

14:03

End Temperature

61

End Cloud Cover

70

End Wind Speed

1-3

Construction Activity and Personnel

19 laborers with hand tools.

What type of monitoring is being conducted?

Restoration Monitoring

Was ESA swept prior to start of work?

Yes

Covered Species Observed?

No

Which Species were observed?

N/A

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Other Wildlife Species Observed

CORA, alligator lizard, CASJ, HOFI

Topics to Cover on the Next Monitoring Day

N/A

Log Entry #1

0713 crew started removing non-native vegetation. 0905, had to reiterate to crew procedures for working in thick mule fat, "only remove veg about an arms length into mule fat, if you need to move branches and there is a chance they may break, you're going too far."

Log Entry #1 - Photos taken?

Yes

Log Entry #1 Photo A



Log Entry #1 Photo B



Log Entry #2

1200 back from lunch, crew cleaning up veg piles pulled earlier and dumping in bins. 1345 swept area for any issues, nothing found. Bio left site at 1405.

Log Entry #2 - Were Photos taken?

Yes

Log Entry #2 Photo A



Log Entry #2 Photo B



Survey Completed?

Yes

Signature

Tom KALIS

Devil's Gate Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 01/11/2019 10:00 AM

Project Name

Devil's Gate Reservoir Restoration Project - 2018-047.009

Date

Jan 11, 2019

Monitor Name

Lauren Simpson

Are Additional Monitors Present?

No

List Additional Monitors Present

N/A

Start Time

06:50

Start Temperature

45

Start Cloud Cover

70

Start Wind Speed

0-3

End Time

09:59

End Temperature

56

End Cloud Cover

70

End Wind Speed

0-3

Construction Activity and Personnel

JV crew, chipping final piles and loading chips into trucks

What type of monitoring is being conducted?

Construction Monitoring

Was ESA swept prior to start of work?

Yes

Covered Species Observed?

No

Which Species were observed?

N/A

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Other Wildlife Species Observed

SOSP, HOFI, OATI, AMCR, CASJ, SAPH, BLPH, Parrot Sp., Gull sp, RTHA, woodrat, western toad, western fence lizard.

Topics to Cover on the Next Monitoring Day

N/A last day of monitoring JV crew.

Log Entry #1

0700 tailboard0725 began observing excavator load stockpiles into chipper. Flushed 1 woodrat, relocated 1 western toad and 1 western fence lizard. 0945 chipper done with stockpiles, only remaining piles are hand picked piles that don't require monitor1010 biologist left site

Log Entry #1 - Photos taken?

Yes

Log Entry #1 Photo A



Log Entry #1 Photo B



Log Entry #1 Photo C



Survey Completed?

Yes

Signature

Devil's Gate Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 01/15/2019 2:01 PM

Project Name

Devil's Gate Reservoir Restoration Project - 2018-047.009

Date

Jan 15, 2019

Monitor Name

Lauren Simpson

Are Additional Monitors Present?

No

List Additional Monitors Present

N/A

Start Time

11:56

Start Temperature

56

Start Cloud Cover

100

Start Wind Speed

1-5

End Time

13:59

End Temperature

52

End Cloud Cover

100

End Wind Speed

1-5 raining

Construction Activity and Personnel

No work in reservoir due to rain

What type of monitoring is being conducted?

Construction Monitoring

Was ESA swept prior to start of work?

Yes

Covered Species Observed?

No

Which Species were observed?

N/A

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Other Wildlife Species Observed

Cora, OATI, BLPH, MALL, CASJ, HOME, YRWA, RTHA, LEGO, ANHU, NOMO, SOSP, CALT, RSHA, NOFL, WRTI, HOFI, ACWO, EUST, Coyote (heard)

Topics to Cover on the Next Monitoring Day

Fix damaged fencing in NW corner and near Alta Dena Drain. Replace ESA signs with something weather proof.

Log Entry #1

1200 onsite for 2x weekly site visit. No construction activities taking place due to rain. Areas where fence is damaged noted. Several 10+ ESA signs retrieved from trail/reservoir. Overall no major issues on-site. All vegetation has been removed, only small amounts of twig debris and dirt piles remain. 1400 left site.

Log Entry #1 - Photos taken?

Yes

Log Entry #1 Photo A



Log Entry #1 Photo B



Log Entry #1 Photo C



Log Entry #1 Photo D



Survey Completed?

Yes

Signature

A handwritten signature in black ink, consisting of a large, stylized 'W' or 'V' shape followed by a horizontal line and a diagonal stroke.

Devil's Gate Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 01/16/2019 1:15 PM

Project Name

Devil's Gate Reservoir Restoration Project - 2018-047.009

Date

Jan 16, 2019

Monitor Name

Lauren Simpson

Are Additional Monitors Present?

No

List Additional Monitors Present

N/A

Start Time

11:41

Start Temperature

56

Start Cloud Cover

100

Start Wind Speed

1-4 raining

End Time

13:30

End Temperature

57

End Cloud Cover

100

End Wind Speed

1-5 raining

Construction Activity and Personnel

No Construction due to rain

What type of monitoring is being conducted?

Construction Monitoring

Was ESA swept prior to start of work?

Yes

Covered Species Observed?

No

Which Species were observed?

N/A

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Other Wildlife Species Observed

ROPI, MODO, CASJ, NOFL, CALT, WEBL, EUST, SAPH, RSHA, YRWA, OATI, SPTO, CORA, BLPH

Topics to Cover on the Next Monitoring Day

Minor fence repairs needed.

Log Entry #1

1140 arrived on site for 2nd of twice weekly site visits. Openings in fence noted along southwest side. 1330 left site, no bio issues observed. Minor fence repairs needed.

Log Entry #1 - Photos taken?

Yes

Log Entry #1 Photo A



Log Entry #1 Photo B



Log Entry #1 Photo C




Log Entry #1 Photo D



Survey Completed?

Yes

Signature

A handwritten signature in black ink, consisting of several overlapping loops and a final upward stroke on the right side.

Devil's Gate Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 01/18/2019 2:36 PM

Project Name

Devil's Gate Reservoir Restoration Project - 2018-047.009

Date

Jan 18, 2019

Monitor Name

Taylor Dee

Are Additional Monitors Present?

No

List Additional Monitors Present

N/A

Start Time

07:00

Start Temperature

48

Start Cloud Cover

15

Start Wind Speed

0-1

End Time

14:30

End Temperature

61

End Cloud Cover

25

End Wind Speed

0-1

Construction Activity and Personnel

Nature's Image crew of 16 with foreman Ron, removing nonnative vegetation by hand-pulling and use of hand tools. Nonnative vegetation removed consisted primarily of perennial pepperweed and mustard.

What type of monitoring is being conducted?

Restoration Monitoring

Was ESA swept prior to start of work?

Yes

Covered Species Observed?

No

Which Species were observed?

N/A

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Other Wildlife Species Observed

CALT, SOSP, AMCR, ANHU, NOFL, BLPH, RTHA, LEWO, CSJA, WEBL, RCKI, WCSP, CATH, BEWR, SPTO, western toad, desert cottontail, SNEG, CORA, HOFI, DEJO, YRWA, ACWO, GBHE, BCSP, MALL, SSHA, MODO, ROPI, SAPH, RSHA, BRBL, southern alligator lizard, southern pacific rattlesnake

Topics to Cover on the Next Monitoring Day

N/A

Log Entry #1

0715 Discussed plan of the day with Ron. Site is very saturated so the crew will focus on west side and avoid the eastern portions that are too wet and muddy. Began monitoring nonnative vegetation removal.

Log Entry #1 - Photos taken?

Yes

Log Entry #1 Photo A



Log Entry #2

0745 As per Carley's suggestion I told Ron that if the crew was limited on areas to work on due to the muddy conditions they could work further north in the alluvial fan sage scrub since it may be dryer or less saturated. He said they may depending on their progress.

Log Entry #2 - Were Photos taken?

No

Log Entry #3

0755 Observed decaying western toad carcass. Bloated and rotting legs. Not projected related.

Log Entry #3 - Were Photos taken?

No

Log Entry #4

0958 Observed construction fencing down on western side. Appears to be caused by the rainfall over the last 3-4 days.

Log Entry #4 - Were Photos taken?

Yes

Log Entry #4 Photo A



Log Entry #5

1045 Crew finished weed pulling and will start clean up and loading debris into burlap bags for disposal after lunch. Relocated 1 alligator lizard and 2 western toads south of where the crew was working to avoid trampling or injury.

Log Entry #5 - Were Photos taken?

No

Log Entry #6

1200 crew began loading removed nonnative vegetation debris into burlap and disposing into bins.

Log Entry #6 - Were Photos taken?

Yes

Log Entry #6 Photo A



Log Entry #6 Photo B



Log Entry #7

1345 Two juvenile southern Pacific rattlesnakes relocated away from crew.

Log Entry #7 - Were Photos taken?

No

Survey Completed?

Yes

Signature

A handwritten signature in black ink, appearing to read "J. M. Lee".

Devil's Gate Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 01/23/2019 12:57 PM

Project Name

Devil's Gate Reservoir Restoration Project - 2018-047.009

Date

Jan 23, 2019

Monitor Name

Taylor Dee

Are Additional Monitors Present?

No

List Additional Monitors Present

N/A

Start Time

07:00

Start Temperature

45

Start Cloud Cover

0

Start Wind Speed

1-2

End Time

09:45

End Temperature

57

End Cloud Cover

0

End Wind Speed

0-1

Construction Activity and Personnel

Twice weekly site visit/inspection

What type of monitoring is being conducted?

Construction Monitoring

Was ESA swept prior to start of work?

Yes

Covered Species Observed?

No

Which Species were observed?

N/A

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Other Wildlife Species Observed

LEGO, AMCR, BLPH, SPTO, HOFI, racoon (tracks), ANHU, parrot sp., CSJA, SOSP, MALL, NOFL, CATH, BUSH, WCSP, CALT, WREN, CORA, EUST, coyote (vocalizations), YRWA, WEBL, ALHU, SAPH, NUWO, BEWR, CAQU, ACWO, RTHA,

Topics to Cover on the Next Monitoring Day

N/A

Log Entry #1

Downed fence: at Alta Dena drainage, along west side just north of entrance from staging area, along road near basins, at northern boundary of initial sediment removal area, along west side and restoration areas.

Log Entry #1 - Photos taken?

Yes

Log Entry #1 Photo A



Log Entry #1 Photo B



Log Entry #1 Photo C



Log Entry #1 Photo D



Log Entry #2

Observed horse tracks in construction site

Log Entry #2 - Were Photos taken?

Yes

Log Entry #2 Photo A



Log Entry #3

0744 observed 2 of Griffith crew drive up and begin working on fence on east side.

Log Entry #3 - Were Photos taken?

No

Log Entry #4

Many parts of fence are strained and partly buried due to high flows during storm last week.

Log Entry #4 - Were Photos taken?

Yes

Log Entry #4 Photo A



Log Entry #4 Photo B



Log Entry #4 Photo C



Log Entry #5

Project signs along fence have washed out of sediment removal area.

Log Entry #5 - Were Photos taken?

Yes

Log Entry #5 Photo A



Log Entry #6

Fence completely washed out along west side toward southern end.

Log Entry #6 - Were Photos taken?

Yes

Log Entry #6 Photo A



Log Entry #6 Photo B



Log Entry #7

0849 observed tractor/small frobt loader witg blade attachment grading road along interor of fence.

Log Entry #7 - Were Photos taken?

No

Log Entry #8

0918 Griffith had repaired many breaks in fence and continues repairs.

Log Entry #8 - Were Photos taken?

Yes

Log Entry #8 Photo A



Survey Completed?

Yes

Signature

A handwritten signature in black ink, appearing to be "J. A. De" or similar, written in a cursive style.

Devil's Gate Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 01/25/2019 1:39 PM

Project Name

Devil's Gate Reservoir Restoration Project - 2018-047.00

Date

Jan 25, 2019

Monitor Name

Taylor Dee

Are Additional Monitors Present?

No

List Additional Monitors Present

N/A

Start Time

12:23

Start Temperature

72

Start Cloud Cover

10

Start Wind Speed

0-2

End Time

13:38

End Temperature

75

End Cloud Cover

0

End Wind Speed

0-1

Construction Activity and Personnel

twice weekly site inspection/visit

What type of monitoring is being conducted?

Construction Monitoring

Was ESA swept prior to start of work?

Yes

Covered Species Observed?

No

Which Species were observed?

N/A

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Other Wildlife Species Observed

CSJA, ANHU, CATH, AMKE, BUSH, SOSP, BLPH, YRWA, racoon (tracks), RCKI, AMCR, coyote, BGGN, SPTO, western side-blotched lizard

Topics to Cover on the Next Monitoring Day

Fence is need of repair/replacement.

Log Entry #1

Multiple areas of downed fence, particularly on western boundary. A major section along the southwestern boundary is missing/washed out and is in need of replacement. Appears to be in same state as site check on Wednesday.

Log Entry #1 - Photos taken?

Yes

Log Entry #1 Photo A



Log Entry #1 Photo B



Log Entry #1 Photo C



Log Entry #1 Photo D



Log Entry #2

Debris (natural and human trash) washed into site from high flows and storm from the previous week. Even tire, metal poles, woody debris...

Log Entry #2 - Were Photos taken?

Yes

Log Entry #2 Photo A



Log Entry #3

Fence remnants littering site.

Log Entry #3 - Were Photos taken?

Yes

Log Entry #3 Photo A



Log Entry #3 Photo B



Log Entry #4

certain areas of the fence are so clogged with debris it may prevent wildlife from moving freely through it.

Log Entry #4 - Were Photos taken?

Yes

Log Entry #4 Photo A



Survey Completed?

Yes

Signature

A handwritten signature in black ink, appearing to be 'M. Ba'.

Devil's Gate Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 01/28/2019 2:04 PM

Project Name

Devil's Gate Reservoir Restoration Project - 2018-047.009

Date

Jan 28, 2019

Monitor Name

Torrey Rotellini

Are Additional Monitors Present?

No

List Additional Monitors Present

N/A

Start Time

07:02

Start Temperature

54

Start Cloud Cover

33

Start Wind Speed

1-3

End Time

14:02

End Temperature

72

End Cloud Cover

15

End Wind Speed

1-3

Construction Activity and Personnel

Restoration activities, crew of 9 with hand tools.

What type of monitoring is being conducted?

Restoration Monitoring

Was ESA swept prior to start of work?

Yes

Covered Species Observed?

No

Which Species were observed?

N/A

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Other Wildlife Species Observed

HOFI, ANHU, AMCO, CASJ, RSHA, western fence lizard, alligator lizard, SAPH

Topics to Cover on the Next Monitoring Day

N/A

Log Entry #1

0703 crew arrived, discussed work plan. Just removing non native species today. Delineated final boundary with Ron (foreman).

Log Entry #1 - Photos taken?

Yes

Log Entry #1 Photo A



Log Entry #1 Photo B



Log Entry #2

1200 back from lunch, crew bagging non native material thy was pulled this morning. Conducted sweep of are at 1355, all piles are being tarred, no issues. Crew cleaning up last of non native material and beginning to dump in trash bins.

Log Entry #2 - Were Photos taken?

Yes

Log Entry #2 Photo A



Log Entry #2 Photo B



Survey Completed?

Yes

Signature

A handwritten signature in black ink, appearing to read 'J. K. Smith'.

Devil's Gate Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 01/29/2019 1:00 PM

Project Name

Devil's Gate Reservoir Restoration Project - 2018-047.009

Date

Jan 29, 2019

Monitor Name

Taylor Dee

Are Additional Monitors Present?

No

List Additional Monitors Present

N/A

Start Time

07:00

Start Temperature

55

Start Cloud Cover

75

Start Wind Speed

0-1

End Time

13:00

End Temperature

73

End Cloud Cover

30

End Wind Speed

0-1

Construction Activity and Personnel

Monitor Nature's Image crew remove nonnative weeds by hand pulling and hand tools.

What type of monitoring is being conducted?

Restoration Monitoring

Was ESA swept prior to start of work?

Yes

Covered Species Observed?

No

Which Species were observed?

N/A

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Other Wildlife Species Observed

BUSH, SPTO, CSJA, WREN, AMCR, EUST, BLPH, WEBL, YRWA, CATH, SOSP, LEGO, RSHA, ANHU, CORA, ACWO, MODO, BEWI, CALT, RTHA, NOFL, CAQU, COHA, western fence lizard, western side-blotched lizard

Topics to Cover on the Next Monitoring Day

N/A

Log Entry #1

0700 NI crew arrived onsite. 0705 WEAP trained 3 new crew members.

Log Entry #1 - Photos taken?

Yes

Log Entry #1 Photo A



Devil's Gate Reservoir Restoration Project
Worker Education Training Program
Sign-in Sheet

By signing your name below, you agree that you attended the Worker Education Training presented by the Project Biologist/Biological Monitor and understand all of the biological issues pertaining to the Devil's Gate Reservoir Restoration Project Site.

Date	Printed Name	Signed Name	Company
11/28/19	MANUEL CONTRERAS	<i>[Signature]</i>	Nature Image
11/28/19	Andres Lopez	<i>[Signature]</i>	" "
11/28/19	Jaguar Painter	<i>[Signature]</i>	Nature Image
11/28/19	Sanchez Jimenez	<i>[Signature]</i>	Nature Image
11/28/19	Daniel Harris	<i>[Signature]</i>	Nature Image
11/28/19	Daniel Harris	<i>[Signature]</i>	Nature Image
11/29	CHRISTIAN ESPANA	<i>[Signature]</i>	Nature Image
8			
9			
10			
11			
12			
13			
14			
15			
16			
17			
18			
19			
20			
21			
22			

Project Biologist/Monitor (print): _____
 Location of Training: _____

Log Entry #2

0715 crew started removing nonnative weeds including posion hemlock, mustard sp., horehound, and perennial pepperweed.

Log Entry #2 - Were Photos taken?

Yes

Log Entry #2 Photo A



Log Entry #2 Photo B



Log Entry #3

1200 Crew began clean up activities. Compiled pulled nonnative vegetation by hand and with rakes to transport in canvas to dumpster.

Log Entry #3 - Were Photos taken?

Yes

Log Entry #3 Photo A



Log Entry #3 Photo B



Log Entry #4

1230 Spoke with Ron and let him know I'd be leaving early. He said they'd try to get everything cleaned up today.

Log Entry #4 - Were Photos taken?

No

Survey Completed?

Yes

Signature

Handwritten signature in black ink.

Devil's Gate Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 01/29/2019 3:14 PM

Project Name

Devil's Gate Reservoir Restoration Project - 2018-047.009

Date

Jan 29, 2019

Monitor Name

Lauren Simpson

Are Additional Monitors Present?

No

List Additional Monitors Present

N/A

Start Time

06:45

Start Temperature

55

Start Cloud Cover

80

Start Wind Speed

0-1

End Time

15:13

End Temperature

70

End Cloud Cover

100

End Wind Speed

0-1

Construction Activity and Personnel

JV land clearing and Griffith. One front loader and 3 crew.

What type of monitoring is being conducted?

Construction Monitoring

Was ESA swept prior to start of work?

Yes

Covered Species Observed?

No

Which Species were observed?

N/A

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Other Wildlife Species Observed

SOSP, WREN, SPTO, Parrot sp, BUSH, AMCR, CALT, CASJ, ANHU, CORA, RTHA, SWTH, NUWO, RCKI, COHA, BLPH, Western fence lizard, shrew, woodrat, BEWR, alligator lizard

Topics to Cover on the Next Monitoring Day

N/A

Log Entry #1

0645 arrived on site 0700 trained 1 new JV crew member. 0730 reviewed work area for day
0830 crew began clearing activities

Log Entry #1 - Photos taken?

Yes

Log Entry #1 Photo A



Log Entry #1 Photo B



Log Entry #2

1230 Clearing activities continued. 1300 Bat tree removed (Salix snag) using special bat method. Tree inspected, no bat or bat sign removed. 1430 oak tree 65 removed. 1500 crew finished for day. 1 western fence lizard and 1 alligator lizard relocated. 4 woodrats and 1 shrew flushed.

Log Entry #2 - Were Photos taken?

Yes

Log Entry #2 Photo A



Log Entry #2 Photo B



Log Entry #2 Photo C



Survey Completed?

Yes

Signature

A handwritten signature in black ink, consisting of several overlapping loops and a trailing line that ends in a small hook.

Devil's Gate Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 01/30/2019 2:07 PM

Project Name

Devil's Gate Reservoir Restoration Project - 2018-047.009

Date

Jan 30, 2019

Monitor Name

Lauren Simpson

Are Additional Monitors Present?

No

List Additional Monitors Present

N/A

Start Time

07:01

Start Temperature

54

Start Cloud Cover

100

Start Wind Speed

0-3

End Time

14:05

End Temperature

79

End Cloud Cover

0

End Wind Speed

0-3

Construction Activity and Personnel

Nature's Image. 10 personnel, raking and hand pulling today

What type of monitoring is being conducted?

Restoration Monitoring

Was ESA swept prior to start of work?

Yes

Covered Species Observed?

No

Which Species were observed?

N/A

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Other Wildlife Species Observed

WCSP, ANHU, BEWR, EUST, AMCR, WREN, NOFL, NUWO, LEGO, MODO, ROPI, CASJ, ACWO, CALT, CATH, SPTO, BGGN, WEBL, HOFI, AMKE, deer mouse, SOS, RTHA, western toad, YRWA, OATI, BLPH, CORA, ALHU, RSHA, western fence lizard, coastal whiptail, BUSH

Topics to Cover on the Next Monitoring Day

N/A

Log Entry #1

0700 arrived on site, heavy fog. Crew hand pulling pepper weed and hemlock and raking previous day's pull. 0900 crew alerted me to a western toad in their work area, relocated it outside of the work area. 1245 crew gathering and tarping bundles 1400 left site for day no bio issues observed.

Log Entry #1 - Photos taken?

Yes

Log Entry #1 Photo A



Log Entry #1 Photo B



Log Entry #1 Photo C



Survey Completed?

Yes

Signature

A handwritten signature in black ink, consisting of a large, stylized 'S' followed by a series of loops and a final horizontal stroke.

Devil's Gate Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 01/30/2019 2:06 PM

Project Name

Devil's Gate Reservoir Restoration Project - 2018-047.009

Date

Jan 30, 2019

Monitor Name

Taylor Dee

Are Additional Monitors Present?

No

List Additional Monitors Present

N/A

Start Time

07:00

Start Temperature

54

Start Cloud Cover

100

Start Wind Speed

0-1

End Time

11:00

End Temperature

59

End Cloud Cover

100

End Wind Speed

0-1

Construction Activity and Personnel

Vegetation removal near western access road.

What type of monitoring is being conducted?

Construction Monitoring

Was ESA swept prior to start of work?

Yes

Covered Species Observed?

No

Which Species were observed?

N/A

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Other Wildlife Species Observed

BLPH, ANHU, SPTO, AMCR, BEWR, HETH, BUSH, MALL, RTHA, SOSP, RSHA, CORA, LEGO, BUSH, CAGO, CASJ

Topics to Cover on the Next Monitoring Day

N/A

Log Entry #1

0700 Met JV Land Clearing crew of 3 onsite at staging area. They planned to finish with vegetation removal early today. They would be working near the western access road.

Log Entry #1 - Photos taken?

No

Log Entry #2

0732 started vegetation removal on western access road for the day. One operator using a dozer to clear vegetation.

Log Entry #2 - Were Photos taken?

No

Log Entry #3

0800 Operator left to get a chainsaw to remove part of tree without damaging vegetation outside the work limits. He returned shortly with the 2 laborers.

Log Entry #3 - Were Photos taken?

No

Log Entry #4

0845 Clarified boundaries and work limits between restoration area and access road with Lauren Simpson and Luke (LACDPW?). Showed crew where vegetation removal limits were.

Log Entry #4 - Were Photos taken?

No

Log Entry #5

0920 Dozer operator loading haul truck with vegetation debris.

Log Entry #5 - Were Photos taken?

No

Log Entry #6

1030 Crew returned to vegetation removal.

Log Entry #6 - Were Photos taken?

Yes

Log Entry #6 Photo A



Log Entry #6 Photo B



Log Entry #6 Photo C



Log Entry #6 Photo D



Log Entry #7

1055 Confirmed with operator that they were done removing vegetation for the day. Laborers loaded the dozer bucket by hand with vegetation debris scattered in the southwestern portion to compile into one pile to haul off site. I let him know I'd be leaving if they were done with vegetation removal.

Log Entry #7 - Were Photos taken?

No

Survey Completed?

Yes

Signature

A handwritten signature in black ink, appearing to be a stylized name or set of initials.