

Devil's Gate Reservoir Restoration Project 2025 Nesting Bird Log (Through August 31, 2025)

Nest ID	Species	Discovery Date	Discovery Stage	Location Description	Buffer Size (ft)	Updates	Update Status	Update Stage
CORA_01	Common raven	2/7/2025	Nest building	Towards the top of tree on the top of the hill. Observed carrying sticks into tree.	80	3/20/2025	Active	Feeding young
						4/8/2025	Active	Feeding young
						5/5/2025	Active	Fledglings close to nest
						5/22/2025	Inactive	Fledged
OATI_01	Oak titmouse	2/21/2025	Nest building	Woodpecker hole in tree along side road, wall side. Branch is facing road with nest entrance visible.	30	6/10/2025	Inactive	Possibly fledged
LEGO_01	Lesser goldfinch	3/17/2025	Nest building	Approx 6ft up in a low hanging branch of a Canary Island Pine in the center median. Female seen brining material to the nest which appeared damaged from the recent storms, but still being built upon.	30	5/2/2025	Inactive	Nest failed
BUSH_01	Bushtit	3/25/2025	Nest building	In eucalyptus, in a low branch that points approximately south, 6 ft above ground. See generic point for best viewpoint location.	30	4/30/2025	Inactive	Nest failed
BUSH_02	Bushtit	3/26/2025	Nest building	Approx. 10ft high in a willow. On the right of maintenance path when facing N.	35	4/10/25	Active	Nest building
						5/8/2025	Inactive	Possibly fledged
ALHU_01	Allen's hummingbird	3/26/2025	Feeding young	Approx. 12 ft up in willow. On the right side of maintenance path when facing North. Observed feeding chicks.	35	4/1/2025	Active	Feeding young
						4/14/2025	Active	Fledglings close to nest
						5/5/2025	Inactive	Fledged

Nest ID	Species	Discovery Date	Discovery Stage	Location Description	Buffer Size (ft)	Updates	Update Status	Update Stage
BUSH_03	Bushtit	3/28/2025	Nest building	Approx 6 ft high in a Mexican elderberry just on the other side of the black irrigation pipe. BUSH are just starting to weave fibers together.	20	4/28/2025	Active	Nest building
						6/17/2025	Inactive	Nest failed
ANHU_01	Anna's hummingbird	3/31/2025	-	15 feet SW of road, potential nest, no nest sighted.	60	4/2/2025	Active	Feeding young
						4/18/2025	Inactive	Fledged
CANG_01	Canada goose	4/2/2025	Incubating	Observed CANG sitting on nest used last year. Stick nest with feathers visible (top layer) Located on east side of the reservoir, near the bridge. More specifically, located on a shelf of the eastern slope (on the portion of the slope that is cemented).	30	4/15/2025	Active	Incubating
						4/25/2025	Inactive	Possibly fledged
MODO_01	Mourning dove	4/4/2025	Incubating	About 10 feet up in Eucalyptus in the fork of a NE facing branch.	30	4/17/2025	Active	Incubating
						5/5/2025	Inactive	Possibly fledged
BUSH_04	Bushtit	4/4/2025	Nest building	Attached 6ft high in a willow. Location photo facing SW, standing next to tiny orange flag.	40	4/10/2025	Active	Nest building
						5/6/2025	Active	Incubating
						5/21/2025	Inactive	Possibly fledged
BEWR_01	Bewick's wren	4/7/2025	Nest building	Two to three feet off ground in (west facing) cavity of log at top	30	4/10/2025	Active	Nest building

Nest ID	Species	Discovery Date	Discovery Stage	Location Description	Buffer Size (ft)	Updates	Update Status	Update Stage
				and center of log pile east of trail and under oak. pair carrying fluffy nesting material into cavity.		5/21/2025	Inactive	Possibly fledged
CASJ_01	California scrub jay	4/7/2025	Nest building	In blue elderberry bush. Nest not visible but nesting building behavior observed. Elderberry bush adjacent to clearing next to rusty sign post. Shrub is below and next to willows and coast live oak.	30	4/21/2025	Active	Nest building
						6/23/2025	Inactive	Possibly fledged
BUSH_05	Bushtit	4/7/2025	Nest building	Pine tree (southernmost) located above reservoir next to walkway.	30	5/8/2025	Inactive	Nest failed
HOFI_01	House finch	4/7/2025	Nest building	Under the electrical box adjacent to pathway on top of the dam. Best viewed from the West End of the dam underneath the pine tree. Observed carrying nesting materials.	30	6/30/2025	Inactive	Possibly fledged
CLSW_01	Cliff swallow	4/7/2025	Incubating	Observed CLSW individual visit nest & feed female in cluster on column.	30	6/30/2025	Inactive	Possibly fledged
WREN_01	Wrentit	4/9/2025	Nest building	About 2 ft off the ground in coyote brush obscured by the leaves. Location photo facing west.	35	5/6/2025	Active	Incubating
						5/21/2025	Inactive	Possibly fledged
CASJ_02	California scrub jay	4/10/2025	Nest building	In East edge of willow, ~8ft off the ground. Two adults bringing sticks to nest.	30	6/23/2025	Inactive	Possibly fledged
ANHU_02	Anna's hummingbird	4/14/2025	Nest building	10 ft high on peeling bark of west facing branch of oak tree that arches over the public trail. Location photo facing ENE. Observed her adding fluff to the inside of the cup.	30	4/25/25	Active	Incubating
						5/5/2025	Inactive	Nest failed

Nest ID	Species	Discovery Date	Discovery Stage	Location Description	Buffer Size (ft)	Updates	Update Status	Update Stage
SOSP_01	Song sparrow	4/14/2025	Incubating	Cup nest in the leaf litter with 1 egg under branches of a black willow and CA wild rose. Location pic facing E. Location pic from trail facing W.	30	4/15/2025	Inactive	Nest failed
BUSH_07	Bushtit	4/14/2025	Nest building	In willow tree on a branch pointing SW behind bundle of leaves. Best seen against edge of bank looking W. BUSH bringing sticks to nest that looks complete.	30	6/19/2025	Inactive	Nest failed
BUSH_08	Bushtit	4/15/2025	Nest building	In oak tree west of the maintenance path. About 20 feet high under foliage of east facing branch.	30	5/7/2025	Active	Incubating
						5/23/2025	Inactive	Nest failed
BEWR_02	Bewick's wren	4/17/2025	Nest building	At the base of the slope under a fan palm frond. Location photo facing N.	45	5/7/2025	Active	Incubating
						5/23/2025	Active	Incubating
						5/28/2025	Inactive	Nest failed
ATFL_01	Flycatcher spp.	4/17/2025	Nest building	Flew into large elderberry tree with flower petal in mouth. It originally perched on mulefat in open clearing and flew N towards a small patch of sunflowers and into the elderberry branches. Most likely ATFL.	50	6/30/2025	Inactive	-
CALT_01	California towhee	4/17/2025	Nest building	In small CA sagebrush. Photo taken at 1210 will show pathway to nest. A few feet in, look N and there is a group of larger sticks. To the right of that is the CA sagebrush. Mostly completed stick nest is about 3 feet off the ground and hidden in sagebrush.	30	6/23/2025	Inactive	Possibly fledged
BUSH_09	Bushtit	4/18/2025	Nest building		30	5/5/2025	Active	Nest building

Nest ID	Species	Discovery Date	Discovery Stage	Location Description	Buffer Size (ft)	Updates	Update Status	Update Stage
				BUSH seen heading to and from nest with material for building. Nest is roughly 7 feet high in arroyo willow.		5/20/2025	Active	Feeding young
						6/12/2025	Inactive	Fledged
CAKI_01	Cassin's kingbird	4/21/2025	Nest building	In cavity of top north facing prong on utility pole. Female observed bringing in nest material, while male stands guard. Potential HOFI nesting on cavity below, due to presence and lots of sticks. Location photo facing N.	30	6/2/2025	Inactive	Nest failed
CALT_02	California towhee	4/22/2025	Nest building	In woodrat nest in between mulefats. Nest not visible but CALT seen depositing nesting material multiple times.	30	6/17/2025	Inactive	Possibly fledged
LEGO_02	Lesser goldfinch	4/25/2025	Feeding young	Observed squirrel go to the nest, take a chick out, and eat it. 8+ LEGO calling at squirrel. Nest may still have other chicks. Located in oak east of permitter trail approx ~30ft high. In branch on N side of tree within dead oak leaves hanging downward.	30	5/5/2025	Inactive	Nest failed
ACWO_01	Acorn woodpecker	4/25/2025	Incubating	Nest cavity approximately 25 feet high in snag of willow tree in DG-4.	30	6/2/2025	Inactive	Fledged
YEWA_01	Yellow warbler	4/25/2025	Nest building	Within an oak tree adjacent to road and at the top of the bank of the creek. Nest is located in the fork of north facing branches approx 30ft high on side of tree closer to the creek. Behind Devils Gate Restoration info sign.	100	5/5/2025	Active	Incubating
						5/15/2025	Inactive	Possibly fledged
CASJ_03	California scrub jay	4/28/2025	Incubating	Going east on the maintenance trail turn north at the tiny orange flag, the location photo is facing	30	6/2/2025	Active	Feeding young
						6/6/2025	Active	Fledglings close to nest

Nest ID	Species	Discovery Date	Discovery Stage	Location Description	Buffer Size (ft)	Updates	Update Status	Update Stage
				east, nest with 4 eggs is 6ft high in an arroyo willow.		6/9/2025	Inactive	Fledged
SPTO_01	Spotted towhee	4/29/2025	Incubating	Hidden beneath base of mule fat tree.	30	5/2/2025	Inactive	Nest failed
CALT_03	California towhee	4/30/2025	Nest building	Interior of mulefat at the base of the plant. See generic point for best viewing location. Crew should walk to the north of this buffer if they need to pass through the area.	30	5/15/2025	Inactive	Nest failed
ALHU_02	Allen's hummingbird	4/30/2025	Incubating	Eight feet up in emergent fig tree. Nest located on south side of fig tree between leaf and trunk. Best viewed from east.	30	6/12/2025	Inactive	Fledged
ALHU_03	Allen's hummingbird	4/30/2025	Incubating	In branch of oak overhanging north facing slope towards reservoir. Nest branch has dead foliage and is on north side of tree. Nest is best viewed from S standing at edge of hill. Nest is 2 feet from bottom of branch foliage.	30	6/10/2025	Inactive	Fledged
CAQU_01	California quail	5/1/2025	Nest building	Next to a log at the base of some mulefat. Marked with faded orange flag. Location photo facing E.	60	6/3/2025	Inactive	Possibly fledged
BEWR_03	Bewick's wren	5/5/2025	Incubating	In right cavity under dumpster door.	30	5/14/2025	Active	Feeding young
						5/22/2025	Active	Feeding young
						5/27/2025	Active	Feeding young
						5/30/2025	Active	Fledglings close to nest
						6/6/2025	Inactive	Fledged
BUSH_10	Bushtit	5/6/2025	Nest building	BUSH pair seen entering nest cavity approximately 3.5 feet high in eastern facing branch of Elder tree.	30	5/21/2025	Active	Incubating
						6/6/2025	Inactive	Nest failed
BUSH_11	Bushtit	5/6/2025	Nest building	Observed BUSH carrying material into cavity approximately 6 feet	30	5/23/2025	Inactive	Nest failed

Nest ID	Species	Discovery Date	Discovery Stage	Location Description	Buffer Size (ft)	Updates	Update Status	Update Stage
				high in willow. Located about 10 feet from the road.				
CALT_04	California towhee	5/8/2025	Nest building	~7 ft up in cottonwood tree.	30	6/4/2025	Inactive	Nest failed
KILL_01	Killdeer	5/8/2025	Incubating	In RAFSS reference site in floodplain of creek.	50	5/30/2025	Inactive	Possibly fledged
BUSH_12	Bushtit	5/8/2025	Nest building	15ft high in arroyo willow, obscured by leaves, in between the maintenance path and public trail.	30	5/23/2025	Inactive	Nest failed
CATH_01	California thrasher	5/8/2025	Nest building	2ft high in sparsely foliated mulfat surrounded my hoary nettle. Just west of maintenance path on small off shoot. About 12 meters west of maintenance trail.	30	5/23/2025	Active	Incubating
						6/13/2025	Active	Fledglings close to nest
						6/23/2025	Inactive	Fledged
OATI_02	Oak titmouse	5/8/2025	Feeding young	In snag just off road approximately 12 feet high in ash tree.	0	6/10/2025	Inactive	Possibly fledged
BHGR_01	Black-headed grosbeak	5/8/2025	Incubating	6ft high in elderberry tree with 2 eggs.	30	5/16/2025	Active	Incubating
						6/6/2025	Inactive	Possibly fledged
CALT_05	California towhee	5/8/2025	Incubating	Incubating 2 eggs 6ft high in fork of black willow.	30	5/16/2025	Active	Incubating
						6/6/2025	Inactive	Possibly fledged
BUSH_13	Bushtit	5/9/2025	Nest building	Observed BUSH carrying material to canopy of Oak tree. Nest partially constructed on southwestern hanging branch approximately 20 feet high. Across from DG-2A, east of the path.	30	5/9/2025	Inactive	Nest failed
BUSH_14	Bushtit	5/9/2025	Nest building	Approximately 12 feet high in western facing Oak branch that hangs over the road.	30	5/20/2025	Inactive	Nest failed
BUSH_15	Bushtit	5/9/2025	Nest building	Approximately 10 feet high in cottonwood tree, adjacent to the road in DG-2.	30	5/16/2025	Inactive	Nest failed

Nest ID	Species	Discovery Date	Discovery Stage	Location Description	Buffer Size (ft)	Updates	Update Status	Update Stage
BHGR_02	Black-headed grosbeak	5/12/2025	Nest building	5 feet up in mule fat. Best seen from the east. Early on in nest building process but stick arrangement can be seen. Put flagging at crew entry points to the east but not encircling nest due to dense veg and nettles.	40	5/28/2025	Active	Incubating
						6/3/2025	Active	Incubating
						7/1/2025	Inactive	Fledged
CALT_06	California towhee	5/12/2025	Feeding young	Unable to locate nest. Within nettle that is between a cluster of several thin, young black willows. Finger in pictures is pointing to general area. Adults were bringing grubs to this area throughout the day.	30	7/1/2025	Inactive	Fledged
CASJ_04	California scrub-jay	5/13/2025	Incubating	Nest tucked under elder branch approximately 5 feet high and 8 feet from the path.	30	5/30/2025	Inactive	Possibly fledged
BUSH_16	Bushtit	5/14/2025	Nest building	In large willow, approx 25 feet above the ground, in branch on north side. Two adults bringing nesting material repeatedly. Cannot see nest.	30	7/8/2025	Inactive	Nest abandoned
CLSW_02	Cliff swallow	5/15/2025	Nest building	CLSW entering and exiting an incomplete looking nest. On support beam immediately east of CLSW-1 underneath light pole and on same beam as CLSW-3. Two nests are located on this beam. Nest being built is nest on west side of beam.	30	08/28/2025	Inactive	Fledged
CLSW_03	Cliff swallow	5/15/2025	Feeding young	CLSW bringing food to nest and staying in nest for a minute at a time. On support beam immediately east of CLSW-1 underneath light pole and on same beam as CLSW-02. Two nests are	30	7/9/2025	Inactive	Fledged

Nest ID	Species	Discovery Date	Discovery Stage	Location Description	Buffer Size (ft)	Updates	Update Status	Update Stage
				located on this beam. This nest is located on east side of beam.				
CALT_07	California towhee	5/16/2025	Incubating	Nest tucked beneath broomsage on hillside about 15 feet from yellow access gate in DG-1.	30	6/16/2025	Inactive	Possibly fledged
BUSH_17	Bushtit	5/16/2025	Nest building	Approximately 12 feet high in Oak tree near main road.	30	6/19/2025	Inactive	Nest failed
BUSH_18	Bushtit	5/16/2025	Nest building	Approximately 10 feet high in Oak. About 10 feet south of BUSH_17.	30	6/17/2025	Inactive	Nest failed
CASJ_05	California scrub-jay	5/19/2025	Incubating	8ft high in mexican elderberry incubating. Lots of vegetation in surrounding area.	25	6/12/2025	Active	Incubating
						6/24/2025	Inactive	Nest failed
BHGR_03	Black-headed grosbeak	5/20/2025	Incubating	Nest fully established 7 feet high in willow. Incubating.	30	6/12/2025	Inactive	Nest failed
MODO_02	Mourning dove	5/22/2025	Nest building	~7ft high on side growing cottonwood trunk.	30	6/2/2025	Inactive	Nest failed
CALT_08	California towhee	5/27/2025	-	15 feet up a willow at the end of an arching branch. The willow is just S/SE of maple tree.	30	6/12/2025	Active	Incubating
						7/8/2025	Inactive	Possibly fledged
SOSP_02	Song sparrow	5/27/2025	Incubating	1 foot high in Xanthium strumarium covered in Cuscuta sp. with 3 eggs.	30	6/17/2025	Inactive	Nest failed
MODO_03	Mourning Dove	5/28/2025	Nest building	Observed MODO pair copulating over trail and pair flew to woodrat nest about 8 foot high in tree. Pair appeared to be moving around sticks, but left after ~5 min.	30	7/18/2025	Inactive	Possibly Fledged
KILL_02	Killdeer	5/28/2025	Incubating	Approximately 40 feet west of the path in the side slopes. Two eggs present.	30	6/6/2025	Active	Incubating
						6/10/2025	Active	Incubating
						6/17/2025	Active	Incubating
						6/23/2025	Active	Incubating
						6/25/2025	Active	Feeding young
						6/26/2025	Inactive	Fledged
ANHU_03	Anna's hummingbird	5/29/2025	Incubating	Cup nest on lowest hanging branch of oak tree across from	30	6/13/2025	Active	Feeding young
						6/17/2025	Active	Feeding young

Nest ID	Species	Discovery Date	Discovery Stage	Location Description	Buffer Size (ft)	Updates	Update Status	Update Stage
				DG-2A, east of the path. ANHU was incubating.		6/26/2025	Inactive	Fledged
PHAI_01	Phainopepla	5/30/2025	Nest building	60ft high on east facing branch of sycamore. Photos facing SE, difficult to see nest without PHAI sitting in it.	50	6/25/2025	Inactive	Nest failed
CALT_09	California towhee	6/3/2025	Nest building	CALT seen coming back and forth to this area over the course of an hour. Had fluffy material in mouth but could have just been foraging on mulefat seeds. In patch of poison hemlock near arched tree.	30	7/11/2025	Inactive	Possibly fledged
CALT_10	California towhee	6/3/2025	Feeding young	In mugwort patch next to bare hill. CALT brought worm here and begging calls erupted.	30	6/30/2025	Inactive	Fledged
CALT_11	California towhee	6/3/2025	Incubating	Nest visible four feet high in willow. CALT incubating two eggs. Location photo facing south.	30	6/9/2025	Active	Nest building
						7/14/2025	Inactive	Nest Failed
YEWA_02	Yellow warbler	6/3/2025	Feeding young	Nest is not visible due to foliage. Located 30 ft above ground in branch of mature oak. Nest is 30 feet east of asphalt. Best viewed standing on slope next to jimson weed, before poison oak.	100	7/7/2025	Inactive	Possibly fledged
CALT_12	California towhee	6/3/2025	Feeding young	CALT carrying worm to this area, cannot locate nest.	30	6/25/2025	Active	Feeding young
						8/5/2025	Inactive	Possibly fledged
CALT_13	California towhee	6/4/2025	Incubating	The nest was found by the crew in a mix of hemlock and CA blackberry. Two blue-ish eggs were inside the nest. The nest is about a foot off the ground. As I set up the buffer I saw an adult CALT go to the nest. The adults remained in the area as I left.	30	6/30/2025	Inactive	Possibly fledged

Nest ID	Species	Discovery Date	Discovery Stage	Location Description	Buffer Size (ft)	Updates	Update Status	Update Stage
CAQU_02	California quail	6/5/2025	Incubating	Underneath pile of dead wood incubating 10 eggs. Location photo facing N.	60	7/3/2025	Inactive	Possibly fledged
CAKI_02	Cassin's kingbird	6/5/2025	Incubating	In top cavity of utility like of west facing projection. Nest visible. Location photo facing W.	30	6/11/2025	Active	Incubating
						7/14/2025	Inactive	Possibly fledged
KILL_03	Killdeer	6/6/2025	Incubating	Within rocky area of riverbed. Incubating 3 eggs.	50	6/10/2025	Inactive	Nest failed
SPTO_02	Spotted towhee	6/9/2025	Feeding young	On ground in blackberry thicket. At least 2 chicks seen in nest bowl and adult observed feeding chicks.	40	6/11/2025	Active	Fledglings close to nest
						7/14/2025	Inactive	Fledged
BCHU_01	Black-chinned hummingbird	6/9/2025	Nest building	7 ft off ground directly adjacent and visible from walking trail; near end of branch on ash tree.	30	6/17/2025	Active	Incubating
						6/27/2025	Active	Incubating
						7/7/2025	Inactive	Nest Failed
CALT_14	California towhee	6/9/2025	Nest building	10-12 ft high in cottonwood.	30	6/11/2025	Active	Incubating
						7/16/2025	Inactive	Possibly fledged
CLSW_04	Cliff swallow	6/10/2025	Incubating	Located on western side of freeway overpass.	30	8/28/2025	Inactive	Fledged
CLSW_05	Cliff swallow	6/10/2025	Incubating	Immediately east of CLSW-04. On overpass.	30	8/28/2025	Inactive	Fledged
CLSW_06	Cliff swallow	6/10/2025	Incubating	Located along over hang of overpass. May seen coming and feeding take on nest.	30	8/28/2025	Inactive	Fledged
CLSW_07	Cliff swallow	6/10/2025	Incubating	Along overhang of road overpass. Directly west of CLSW-06.	30	8/28/2025	Inactive	Fledged
CLSW_08	Cliff swallow	6/10/2025	Incubating	On side of road overpass overhang. Make seen coming to and from nest to feed female.	30	8/28/2025	Inactive	Fledged
GHOW_01	Great horned owl	6/10/2025	Fledglings close to nest	Two chicks observed in oak South of dam, north of overpass. No nest observed.	300	8/28/2025	Inactive	Fledged
KILL_04	Killdeer	6/10/2025	-	Kill deer showing broken wing display and around area. Nest pointy south of rock pile in northern area of reservoir.	50	6/19/2025	Inactive	Nest failed

Nest ID	Species	Discovery Date	Discovery Stage	Location Description	Buffer Size (ft)	Updates	Update Status	Update Stage
CALT_15	California towhee	6/11/2025	-	Probable CALT nest. CALT flying back and forth from this point in tall hemlock patch and chirping loudly on nearby willow. It would silently fly into the hemlock patch & remain there for longer periods of time. Did not flag off but assuming there's a nest.	30	6/25/2025	Inactive	Possibly fledged
CASJ_06	California scrub-jay	6/12/2025	Feeding young	Mid-size, sloppy cup nest in ash tree, on lower horizontal branch, at fork in branch. Observed adult feeding young.	30	6/13/2025	Active	Possibly fledged
						6/16/2025	Active	Possibly fledged
						6/25/2025	Inactive	Fledged
MODO_04	Mourning dove	6/13/2025	Incubating	About 7 ft off the ground on Mulefat. Nest is next to cotton wood tree. Photo direction facing 10ft SE from flagging tape with white sticker and maintenance trail.	30	6/24/2025	Inactive	Possibly fledged
SPTO_03	Spotted towhee	6/16/2025	Incubating	Three egg cup nest within leaf litter covered by Datura wrightii and Artemisia douglasiana. Location photo facing SE, taken from orange bow.	40	6/23/2025	Active	Incubating
						7/2/2025	Active	Incubating
						7/7/2025	Inactive	Nest failed
MALL_01	Mallard	6/17/2025	Fledglings close to nest	Mobile nestlings on edge of water still in process of dying down.	0	6/23/2025	Active	Fledglings close to nest
						7/9/2025	Inactive	Fledged
CANG_02	Canada goose	6/17/2025	Fledglings close to nest	Pair with 5 nearly grown juveniles, will be fledged in next week or 2.	0	6/23/2025	Active	Fledglings close to nest
						6/25/2025	Active	Fledglings close to nest
						7/9/2025	Inactive	Possibly fledged
MALL_02	Mallard	6/17/2025	Fledglings close to nest	Female with 5 1- week old fledglings on water.	0	6/24/2025	Active	Fledglings close to nest
						7/9/2025	Inactive	Fledged
KILL_05	Killdeer	6/17/2025	Fledglings close to nest	On dried down apron 200' from water, 2 mobile hatchlings, 6 adults in immediate area.	300	6/23/2025	Inactive	Fledged

Nest ID	Species	Discovery Date	Discovery Stage	Location Description	Buffer Size (ft)	Updates	Update Status	Update Stage
ANHU_04	Anna's hummingbird	6/17/2025	Incubating	In bare, hanging oak branches ~25 feet east of walking path, 10 feet above ground level. Female sitting on nest.	30	6/24/2025	Active	Feeding young
						7/2/2025	Inactive	Possibly fledged
LEGO_03	Lesser goldfinch	6/18/2025	Feeding young	7' above ground in outer CLO branch overhanging asphalt roadside ditch.	30	7/7/2025	Inactive	Fledged
MODO_05	Mourning dove	6/24/2025	Nest building	5ft high in mulefat. Location photo facing SE taken from orange flag on arroyo willow.	30	7/10/2025	Inactive	Possibly fledged
CALT_16	California towhee	6/27/2025	Incubating	East of the road about 4 feet high in willow tree.	30	7/3/2025	Active	Feeding young
						7/7/2025	Active	Feeding young
						7/9/2025	Inactive	Possibly fledged
KILL_06	Killdeer	6/30/2025	Incubating	On open ground in shade of emergent Xantium, will be quickly overgrown in next few weeks.	50	7/9/2025	Inactive	Possibly fledged
CLSW_09	Cliff swallow	6/30/2025	-	On north facing side of bridge under overhanging, at least 4 active nests unlikely to be affected by project.	30	7/9/2025	Active	Feeding young
						8/28/2025	Inactive	Fledged
CLSW_10	Cliff swallow	6/30/2025	-	Several agitated cliff swallow at least 5 active nests on outer south side of bridge under overhanging, some near fledged sitting on edge of nest.	30	7/9/2025	Active	Feeding young
						8/28/2025	Inactive	Fledged
ACWO_02	Acorn woodpecker	7/3/2025	Feeding young	18 feet above ground level in cavity located immediately below lowest broken branch where it connects to trunk, view from trail to west, not flagged as nest is close to fledging and not in immediate danger.	30	7/15/2025	Active	Feeding young
						8/5/2025	Inactive	Possibly fledged
LEGO_04	Lesser goldfinch	7/7/2025	Feeding young	13' above ground level in outer lowest branch of black willow that is arching southward, blue/white	30	-	-	-

Nest ID	Species	Discovery Date	Discovery Stage	Location Description	Buffer Size (ft)	Updates	Update Status	Update Stage
				flagging added to red/ white flagging already in place to north.				
ACWO_03	Acorn woodpecker	7/7/2025	Feeding young	In willow about 15 feet high, just above knotted elbow of tree with multiple branches.	30	7/8/2025	Active	Feeding young
						8/5/2025	Inactive	Possibly fledged
BHGR_04	Black-headed grosbeak	7/9/2025	Feeding young	13' above ground level in SW side of 25' tall willow, visible from upper trail to south and also from trail below to east.	30	7/11/2025	Active	Fledglings close to nest
						7/31/2025	Inactive	Fledged
HOFL_02	House finch	7/14/2025	Nest building	On utility pole cavity ~40-50 meters high. Cavity is on west facing prong, 3rd prong from the top.	30	7/16/2025	Active	Nest building
						8/27/2025	Inactive	Nest abandoned
MODO_06	Mourning dove	7/17/2025	Incubating	Four feet high in broken cottonwood stump. Photo facing south.	30	8/6/2025	Inactive	Possibly fledged
LEGO_05	Lesser goldfinch	7/23/2025	Feeding young	~12ft up on hanging branch of oak adjacent to paved path.	30	8/8/2025	Inactive	Fledged
SOSP_03	Song sparrow	7/29/2025	-	In patch of veg that includes mulefat, mugwort, rose, and a small young cottonwood.	30	-	-	-
ACWO_04	Acorn woodpecker	8/6/2025	Feeding young	20 ft off ground in south-facing cavity of cottonwood tree	30	8/15/2025	Active	Feeding young