T.3 N.R.15W.

T.3 N.R.14W.

SEC. 24

SEC. 19

F.D. 9139

F.D. 3139

N 89° 27' 05" W 2629.06

N 89° 27' 20" E 2638.06

N 89° 46' 10" E 2636.00

N 89° 27' 40" W 2621.79

N 0° 04' 05" E 2662.62

N 2° 57' 40" W 1033.71

N 2° 57' 40" W 2244.63

N 1° 55' 30" W 2663.74

N 1° 55' 30" W 3064.15

S 89° 49' 10" E 3209.38

S 89° 11' 50" E 5723.63

S 89° 20' 10" W 2794.63

MARGINAL MAP
SCALE 1:24

FOR MORE RECENT SEE

RANCHO EX MISSION

U.S. SURVEY

Section Corner Established
Mound of rock 16"x16"x8" marked SCR. CC. on the east, 3 notches on the north, 3 notches on the south, mound of rocks 3 feet N. the spot (FD.&R.-119)

Closing Corner Established
Mound of rock 16"x16"x8" marked SCR. CC. on the east, 3 notches on the north, 3 notches on the south, mound of rocks 3 feet N. the spot (FD.&R.-119)

Mid. Cor. Established
Concrete, marked

Mid. Cor. Section 19
Concrete, marked

Section Corner Established
Mound of rock 16"x16"x8" marked SCR. CC. on the east, 3 notches on the north, 3 notches on the south, mound of rocks 3 feet N. the spot (FD.&R.-119)

Section Corner Established
Mound of rock 16"x16"x8" marked SCR. CC. on the east, 3 notches on the north, 3 notches on the south, mound of rocks 3 feet N. the spot (FD.&R.-119)

Mid. Cor. Section 19
Concrete, marked

Mid. Cor. Section 19
Concrete, marked

Mid. Cor. Section 19
Concrete, marked

MAP SHOWING
PORTION OF RANGE LINE
BETWEEN RANGES 14 AND 15 WEST IN TOWNSHIP 3 NORTH S.B.M.

County Surveyor's Map No. 8273

J. E. ROCKHOLD COUNTY SURVEYOR

SURVEYED MAR. & APR. 1921.

SCALE 1"=400'

Surveyed under instructions of the Board of Supervisors per order dated Mar. 2, 1921.
Bearings based on Solar observation taken by L.A.Co. Flood Control Dept.

F.B. 61-117 TO 128

Field work by Waite
Office work by Stoddard
Checked by A. Thomas.

A	2	CS	8273
OF			
A	2		

Sht. 16
Sht. 2

On 8-11-21 Set 2" Iron Pipe in concrete, with Brass Cap marked Built Rock Mound. (F.B. 61-121)

¼ Sec. Cor. Established by proportion between N.E. Cor. Sec. 18 and closing cornerstone at N.W. Cor. of Sec. 18.

S 89° 49' 10" E 2643.76' (2640 - Sickler)

F.D. 9139 — 13

Section Corner. Found 2" iron pipe in mound of rock. Set by L.A.Co. Flood Control Dept. in place of 3x3 stake which was destroyed by the late Coast Fire. (R.D. 9139-6) (F.B. 61-122) On 8-11-21 replaced old iron pipe with a 2" iron pipe set in concrete, with Brass Cap marked Built Rock Mound (F.B. 61-122)

Old 3x3" stake mentioned above was the original monument set by U.S. Dep. Surveyor Sickler in 1902. See F.D. 9139-9.

N 0° 10' 50" E 2642.94'

S 0° 10' 50" E 2278.18' (2278.00 - Sickler)

Wit. Cor. Found rock 18"x8"x6" in ground 8 feet of mound of rock. Corner marked WC 4 on the west face. Bearings. On 8-18-21 Replaced rock with 2" Iron Pipe set in concrete, with Brass Cap marked Survey marker rock by side of Iron Pipe and Built Rock Mound. (F.B. 61-122) (R.D. 9139-6)

The rock found here was the original witness corner established by U.S. Dep. Surveyor Sickler in 1902. See F.D. 9139-9.

S 89° 11' 50" E 2657.66 (442.00) 1672.00

S 0° 23' 50" E F.D. 9139-9

SEC. — 18

Post ¼ Cor. Section 18. Established at record distance from Wit. Cor.

N 0° 03' 00" W 2627.33

S 0° 36' 34" E 2674.94' (2662.00 - Sickler)

Sec. Cor. Established by proportion between N.E. Cor. Sec. 19 and closing Corner Stone at N.W. Cor. of Sec. 19

N 89° 47' 20" E 2677.43 (2640 - Sickler)

F.D. 9133 - 12, 13

On 8-19-21 Set 2" Iron Pipe in concrete, with Brass Cap marked Built Rock Mound. (F.B. 61-122) Is located on top of high ridge.

4.00

Section Corner. Found an oak tree and bearing trees. (R.D. 9133-9) (F.B. 61-122) On 8-18-21 Set 2" Iron Pipe in Concrete at Southeast root tree. Pipe has Brass Cap marked Built Rock Mound. (F.B. 61-122) The above found tree is the original monument established by U.S. Dept. Surveyor Sickler in 1902. See F.D. 9139-7,8. The set brass capped monument is set here, and is not the Section Corner but is a witness monument.

N 0° 00' 20" E 2668.24

S 0° 27' 50" W 2659.20 (2660 - Sickler)

Found 2x2 stake set by L.A.Co. Flood Control Dept.

X on rock set by County Surveyor. (R.D. 61-119)

Road ¼ Cor. Section 19

N 89° 40' 00" E 2633.26

F.D. 9139-7, 8

SEC. — 19

Wit. Cor. On 8-19-21 Set 2" Iron Pipe in Concrete, with Brass Cap marked Built Rock Mound. (F.B. 61-123)

On 8-16-21, Replaced Marked Rock with 2" Iron Pipe set in concrete, with Brass Cap marked Survey marker Rock by side of Iron Pipe and Built Rock Mound. (F.B. 61-123)

Sec. Cor. Found oak 48" dia. 18" in ground, mk. ¼ on N. face. Mound of rock 48" south. (R.D. 9133) (F.B. 61-123)

N 0° 00' 20" E 2668.18

The found stone here was the original monument set by U.S. Dep. Surveyor Sickler in 1902. See R.D. 9139-12

On 8-16-21, Replaced Wit. Rock with 2" Iron Pipe set in concrete, with Brass Cap marked Survey marker Rock by side of Iron Pipe and Built Rock Mound. (F.B. 61-123) (R.D. 9139-6)

Found rock in mound of rocks. (F.B. 61-123) (R.D. 9139-6)

S 0° 27' 50" W 2659.20 (2660 - Sickler)

Above found oak scribed "O" the original monument set by U.S. Dep. Surveyor Sickler in 1902. See F.D. 9139-6

(18.00 - Sickler) 1794.63

N 89° 10' 20" W (2640.00 - Sickler) 2634.76'

F.D. 9133 - 11, 12