Found 2" iron pipe centered with spike in concrete in rock mound. North West Corner of Section 26 per Torrens Certificate No B.G.21,109 F.B. 134-46, 83

SECTION CORNER
Found 1" iron bar in mound of rock. Replaced 1" iron bar with 2" iron pipe set in concrete, 12" below surface, with brass cap marked:- See C.S. B-418 F. B. 134-83

COUNTY SURVEYORS T.8N. R.27+26 W. Sec. Cor. MONUMENT

N0°-28'-05"W 20.74'

N.89°-27'-00E. 2659.86'

N.89°-38'-10"-E. 2663.44' C.S.B-830-2

Found 2" iron pipe centered with spike and set in concrete North 1/4 Corner Section 26 per Torrens Certificate No. B.G. 21109 F.B. 134-46.

N.0°-25'-05"W-29.38'

SECTION LINE

N.89°-38'-10"-E. 2663.44' C.S.B-418

SECTION CORNER
Found old 1"x2" stake. Replaced 1"x2" stake with 2" iron pipe, set in concrete, 12" below surface with brass cap marked:- See C.S. B418. F.B. 134-37, 99.

COUNTY SURVEYORS T.8N. R.23+24 W. 24+25 MONUMENT

1/4 SECTION CORNER
Set by proportion as per C.S. B-418. Set 2" iron pipe in concrete, 12" below surface, with brass cap marked:- F.B. 134-100

COUNTY SURVEYORS T.8N. R.14W. 2+3 25+26 1/4 Sec. Cor. MONUMENT

50.74'

47.18'

2646.84'

2640.47'

2640.59'

2646.43'

TORRENS CERTIFICATE Nº B.G.-21109

N.1°-12'-25"W.

N.0°-28'-05"W.

N.1°-07'-10"W.

N.0°-25'-05"W.

2634.92'

N.1°-01'-35"W.

C.S.B-418

C.S.B-418

Found 2" iron pipe in concrete in rock mound W. 1/4 Corner of Section 26 per Torrens Certificate No. B.G.-21109 F.B. 134-83.

S.89°-34'-45"W-19.11'

Found 2" iron pipe set in concrete. Center of Section 26 per Torrens Certificate No. B.G. 21109. F.B. 134-46.

1/4 SECTION CORNER
Set by proportion as per C.S.B-418. Set 2" iron pipe in concrete 12" below surface with brass cap marked:- F.B. 134-83

COUNTY SURVEYORS T.8N. R.27+26 W. 1/4 Sec. Cor. MONUMENT

N. 0°-28'-05"W.-26.79'

S.89°-34'-45"W. 2651.55'

N.89°-30'-10"E. 2659.32'

23.28'

1/4 SECTION LINE

N.89°-30'-10"E.

1/4 SECTION CORNER
Set by proportion per C.S.B 418 Set 2" iron pipe in concrete, 12" below surface, with brass cap marked:- F.B. 134-99.

COUNTY SURVEYORS T.8N. R.26+25 W. 1/4 Sec. Cor. MONUMENT

CENTER OF SECTION
Determined by calculation Nothing Set.

SECTION LINE

SECTION LINE

1/4 SECTION LINE

SECTION LINE

N.1°-12'-25"W. 2646.84' C.S.B-830-2

N.1°-07'-10"W.

N.1°-01'-35"W. C.S.B-830-2

SECTION CORNER
Set by proportion as per C.S.B.418. Set 2" iron pipe in concrete 12" below surface with brass cap marked:- F.B.134-82

COUNTY SURVEYORS T.8N. R.27+26 W. 2+35 MONUMENT

N89°-22'-05"E. 2655.08'

C.S.B-830-2

SECTION LINE

N. 89°-22'-05"E. 2655.08'

C.S.B-418

1/4 SECTION CORNER
Set by proportion as per C.S.B-418. Set 2" iron pipe in concrete 12" below surface with brass cap marked:- F.B. 134-98.

COUNTY SURVEYORS T.8N. R.14W. 2+3 35+36 1/4 Sec. Cor. MONUMENT

SECTION CORNER.
Set by proportion as per C.S.B.418. Set 2" iron pipe in Concrete, 12" below surface, with brass cap marked:- F.B.134-97.

COUNTY SURVEYORS T.8N. R.26+25 W. R.25+36 MONUMENT

N

MAP OF

SECTION 26-T. 8N. R. 14 W.

SHOWING RELATIONSHIP BETWEEN SECTION CORNERS AND LINES ESTABLISHED BY THE COUNTY SURVEYOR AND THOSE ESTABLISED ON THE SURVEY FOR TORRENS CERTIFICATE B.G. 21109

COUNTY SURVEYORS MAP Nº B-667

SCALE 1 INCH=300FT.
SCALE OFFSETS 1 INCH=50FT.

WORK ORDER Nº 107

J. E. ROCKHOLD COUNTY SURVEYOR

SURVEYED APRIL 1929

BEARINGS ARE SAME AS THOSE SHOWN ON C.S. B-418

F. B. 134-46, 51, 82, 98, 99.100

FIELD WORK BY..... E. A. ROSECRANS
OFFICE WORK BY..... H. H. REYNOLDS
CHECKED BY..... K. R. McPHERSON

Sht. 72

NOTE:
The boundaries of the property per Torrens Certificate Number B. G. 21109 are outlined in blue.

CSB-667
A1 OF A1