MARGINAL MAP
SCALE-1 INCH - 600 FT

MAP OF
LLANO CUT-OFF
165TH FROM 167TH STREET EAST
TO
FORT TEJON ROAD

COUNTY SURVEYORS MAP NO B-1573
SHEET NO 1 OF 2 SHEETS
SCALE - 1 INCH = 100 FT

JOB NUMBER 8278.

ALFRED JONES-COUNTY SURVEYOR
SURVEYED OCT. & NOV. 1939

SURVEYED AT VERBAL REQUEST OF THE COUNTY ROAD COMMISSIONER PER RULE 21. ORDINANCE 929. FOR THE PURPOSE OF ESTABLISHING AN OFFICIAL CENTER LINE FOR THE PRESENT TRAVELED ROAD BEARINGS ARE BASED ON THE BEARINGS OF SECTION LINES AS SHOWN ON C.S.B-1572-1.

F.B. 537-15 & 70 & 222.

FIELD WORK BY E.A. ROSECRANS.
OFFICE WORK BY K.R. McPHERSON.
H.U.M. HIGGINS.
CHECKED BY K.R. McPHERSON.

INDEX NO 67.

CSB-1573-1
A1 OF A3

SECTION CORNER
Set 4" iron pipe in concrete, 18" below surface, cap shown in P.B. 53-7, R.O.W. Pipe has aluminum cap marked: See C.S.B. 1572-1, P.B. 237-102, 103, 108

1/4 SECTION CORNER
Located by proportion between Section Corners. Set 4" iron pipe in concrete, 18" below surface with a Brass cap marked: See C.S.B. 1572-1, P.B. 237-108

SECTION CORNER
Found 1" iron pipe set in concrete per P.B. 53-7, R.O.W. and replaced same with a 4" iron pipe set in concrete with brass cap marked: See C.S.B. 1572-1, P.B. 237-108, 103, 107

1/4 SECTION CORNER
Found 1" iron pipe set in concrete with brass cap marked per P.B. 79-91, R.O.W. See C.S.B. 1572-1, P.B. 237-108, 108, P.B. 7988 - 108

1/4 SECTION CORNER
Found 1" iron pipe plug and tack per P.B. 53-7, R.O.W. and replaced same with a 4" iron pipe set in concrete with brass cap marked: See C.S.B. 1572-1, P.B. 237-108

SECTION CORNER
Found 1" iron pipe plug and tack per P.B. 53-7, R.O.W. and replaced same with a 4" iron pipe set in concrete with brass cap marked: See C.S.B. 1572-1, P.B. 237-108

SECTION CORNER
Found 1" iron pipe set in concrete per P.B. 53-7, R.O.W. See C.S.B. 1572-1, P.B. 237-108, 108

1/4 SECTION CORNER
Found 1" iron pipe set in concrete with brass cap marked per P.B. 79-91, R.O.W. See C.S.B. 1572-1, P.B. 237-108, 108, P.B. 7988 - 108

1/4 SECTION CORNER
Found 1" iron pipe plug and tack per P.B. 53-7, R.O.W. and replaced same with a 4" iron pipe set in concrete with brass cap marked: See C.S.B. 1572-1, P.B. 237-108

SECTION CORNER
Found 1" iron pipe set in concrete per P.B. 53-7, R.O.W. See C.S.B. 1572-1, P.B. 237-108, 108

CSB-1573-1
A 2 OF A 3


Section line per C.S.B. 1572-1

Section line and Center line per C.S.B. 1572-1

Section Line

C.S.B. 1572-1

28 27
33 34



CSB-1573-1
A3 OF A3