SECTION CORNER Found County Surveyor's Monument marked: See C.S.B-128-1, F.B. 2336-189
COUNTY SURVEYORS R17W 22 23 27 26 T1S MONUMENT
Set 1" iron pipe & brass tag marked: "L.A.CO.ENGR." F.B. 2336-188
1/4 SECTION CORNER Found County Surveyors Monument marked: See C.S.B-128-1 F.B. 2336-188
COUNTY SURVEYORS R17W 1/4 SEC.COR. 23 26 T1S MONUMENT
N89°40'50"E - (2626.30) per C.S.B-945
2409.93
216.37
N89°40'10"E - (2629.51) per C.S.B-945
Section Line
263.97
Set 1" iron pipe & brass tag marked "L.A.CO.ENGR." F.B. 2336-190
N0°14'10"E - (2597.19) per C.S.B-128-1,2
2333.32
Section Line
SECTION CORNER Found County Surveyors Monument marked: Flush with surface. See C.S.B-525 F.B. 2336-126, 184
COUNTY SURVEYORS R17W 23 24 26 25 T1S MONUMENT
N88°51'55"W - (2679.61) per C.S.B-525
1/4 SECTION CORNER Found County Surveyors Monument marked: See C.S.B-525 F.B. 2336-99, 127
COUNTY SURVEYORS T1S R17W SEC. 24 SEC. 25 MONUMENT
N89°47'30"W - (2626.18) per C.S.B-525
SECTION CORNER Found County Surveyors Monument marked: See F.B. 524-25, C.S.B-2499 F.B. 2336-99
Set 1" iron pipe & brass tag marked "L.A.CO.ENGR." F.B. 2336-174
COUNTY SURVEYORS T1S R17W 24 19 25 30 MONUMENT
25.69
818.13
~~N89°50'05"W~~ N89°51'12"W ~ 2627.59
3512.59
2602.30
Section Line
Transit ~~Section~~ Line
Found Sandstone Rock 6" above surface marked "1/4" on North face. See F.B. 609-224 F.B. 2336-169 Removed, May 1966. F.B. 2336-227
Set 1 1/2" iron pipe with brass tag marked "L.A.CO.ENGR." F.B. 2336-167
0.65
N89°38'47"W 885.00
726.73
158.27
0.15
N12°42'55"W
N12°42'55"W - 889.65
TRIANGULATION STATION TUNA Found 4" brass tablet set in concrete flush with surface marked which replaced U.S.G.S. Bronze tablet cemented in boulder. Set in place by "Steele" in 1925, which replaced found 4"x4" post scribed B.M. See F.M. 18711. F.B. 2336-164
COOPERATIVE SURVEY CONTROL TRIANGULATION OF LOS ANGELES CITY OF LOS ANGELES COUNTY ORIGINALLY ESTABL'D BY U.S.G.S. TUNA 1933 R.E. 62 STATION
CLOSING CORNER Found County Surveyor Monument marked: See F.B. 609-223, F.B. 2336-163
COUNTY SURVEYOR T1S R16W RE 2177
RANCHO CORNER Nº 21 Found County Surveyor Monument marked: 6" above surface See F.B. 609-223 F.B. 2336-111, 169
COUNTY SURVEYOR Nº 21 R.B.S.M. SEC. 30 RE 2177
1/4 SECTION CORNER Found County Surveyors Monument marked 1' below surface. See F.B. 609-224 F.B. 2336-169 Removed & reset 0.65 northerly at correct 1/4 Section Corner. May 1965 F.B. 2336-227
COUNTY SURVEYORS T1S R16W SEC. 19 SEC. 30 1/4 COR. MONUMENT
Set 1" iron pipe & brass tag marked "L.A.CO.ENGR." F.B. 2336-98
349.32
Found 3/4" iron pipe, conc. plug & copper wire, see F.B. 1848-12, replaced same with 1" iron pipe & brass tag marked "L.A.CO.ENGR." F.B. 2336-97
5237.32
1246.77
Found 3/4" iron pipe, conc plug & nail see F.B. 1848-12, replaced same with 1" iron pipe & brass tag marked "L.A.CO.ENGR." F.B. 2336-94
204.12
WITNESS CORNER Set County Engineer Monument marked: F.B. 2336-94
COUNTY ENGINEER R.E. 5869
370.32
1/4 SECTION CORNER Established at mid-point between found Section Corners per C.S. 9237. Terrain unstable, nothing set. F.B. 2336-93
241.27
WITNESS CORNER Set County Engineer Monument marked: F.B. 2336-92
COUNTY ENGINEER R.E. 5869
26
25
30
29
R 17 W
R 16 W
6025.23
N12°20'20"W 4393.92
WLY BOUNDARY RANCHO BOCA DE SANTA MONICA R 3 - 12, 13
1/4 SECTION CORNER Found County Surveyors Monument marked: See C.S.B-128-1 F.B. 2336-115, 191
COUNTY SURVEYORS R17W 1/4 SEC.COR. SEC.27 SEC.26 T1S MONUMENT
50.14
Set 1" iron pipe & brass tag marked: "L.A.CO.ENGR." F.B. 2336-115, 191
1/4 SECTION CORNER Found County Surveyor's Monument marked: F.B. 373-40, F.B. 2336-81, 125, 182
COUNTY SURVEYORS R17W 1/4 SEC. 26 25 T1S MONUMENT
67.80
194.49
307.96
Set 1" iron pipe & brass tag marked "L.A.CO.ENGR." flush with surface. F.B. 2336-80, 81
2649.37
867.07
Set 1" iron pipe & brass tag marked: "L.A.CO.ENGR." flush with surface. F.B. 2336-79
N0°04'25"E - (2636.48) per C.S.B-128-1
Section Line
N0°13'10"E
1212.05
Found 2" iron pipe, wood plug & tag marked "L.S. 2572" 8" above surface. No reference F.B. 2336-77
N0°19'50"E - (2330.46) per C.S.B-128-1
2280.19
Nothing set
T.M. Nº 3 Found County Surveyors Monument marked 3' below surface. See F.B. 2146-105 C.S.B-126-1 F.B. 2336-39
COUNTY SURVEYORS T1S SEC. 27 R.G.T.M.S. T.M.Nº3 MONUMENT
NE'LY BOUNDARY RANCHO TOPANGA MALIBU SEQUIT PER F.B. 3101-91, 99
NE'LY BOUNDARY RANCHO TOPANGA MALIBU SEQUIT PER C.S.B - 539
N84°20'22"W - (4541.64) per F.B. 3101-91, 99
3927.17
614.47
550.46
N84°21'05"W - (614.46) per C.S.B-539
0.13
RANCHO TOPANGA MALIBU SEQUIT
P.1 - 414 - 416
T.M. Nº 2 Rancho "Topanga Malibu Sequit" P.1-414 NE Found County Surveyor's Monument marked: See C.S.B-539 F.B. 2336-118
COUNTY SURVEYORS T1S SEC.26 R.G.T.M.S. T.M.Nº2 MONUMENT
Found Sandstone Rock 8"x18" up 14" marked "X" on West face "WC 26 35" on East face. See F.M. 18617 F.B. 2336-119
Found Sandstone Rock marked "1/4 1/4" on North face, "RCQ" on West face & "X" on top. See F.M. 18617 F.B. 2336-121
N20°05'29"W 290.10
E'LY
61.00
208.62
285.20
47.63
0.18
BOUNDARY RANCHO TOPANGA MALIBU SEQUIT PER C.S.B-539
CLOSING CORNER Found County Surveyor's Monument marked: See C.S.B-128-1, F.B. 2336-115
COUNTY SURVEYORS R17W C.C. SEC.26 R.G.T.M.S. T1S MONUMENT
Corner of Fire Station property. Found County Surveyor's Monument marked: See C.S.B-539, F.B. 298-32 F.B. 2336-116
COUNTY SURVEYORS N.W. COR. OF FIRE STA.
Set lead, tack & brass tag in conc. footing marked "L.A.CO.ENGR." by intersecting line of record angle from the Northwest per C.S.B-539 F.B. 2336-119
Set 1" iron pipe & brass tag marked "L.A.CO.ENGR." F.B. 2336-120
N89°44'25"E - 1866.68
983.00
342.23
Set 1" iron pipe & brass tag marked "L.A.CO.ENGR." F.B. 2336-123
1/4 SECTION CORNER Found Sandstone Rock 15"x9" marked "1/4" on North face. See C.S.B-95134, F.B. 2669-225. Replaced same with County Engineer Monument marked: F.B. 2336-123
COUNTY ENGINEER T1S R17W SEC. 26 SEC. 35 1/4 COR. R.E. 5869
N89°15'35"W - (2643.54) per F.B. 2669
Section Line
258.56
191.08
0.07
262.76
SECTION CORNER Found County Surveyors Monument marked: flush with surface. See F.B. 373-36B F.B. 2336-78, 124
COUNTY SURVEYORS R17W 26 25 35 36 T1S MONUMENT
Found 3/4" iron pipe & tag marked "L.S. 2572" 1" above surface F.B. 2336-77
N89°44'45"W - 2700.25
981.23
291.31
272.68
442.63
Set 1" iron pipe with brass tag marked "L.A.CO.ENGR." flush with surface. F.B. 2336-74, 76
Set 1" iron pipe & brass tag marked "L.A.CO.ENGR." flush with surface F.B. 2336-72, 73
63.85
24.05
1/4 SECTION CORNER Found Sandstone Rock 8"x10"x18" above surface. Marked "1/4 S" on North face. See C.S. 9237-7 & Replaced same with County Engineer Monument marked "A" F.B. 2336-73 above surface.
COUNTY ENGINEER 1/4 COR. SEC. 25 SEC. 36 T1S R.E. 5869
N89°56'45"W - 2604.37
1722.35
300.02
178.59
299.51
Set 1" iron pipe, conc. plug & brass tag flush with surface marked "L.A.CO.ENGR." F.B. 2336-70
SECTION CORNER Found County Surveyor's Monument marked: 4" above surface in rock mound. See F.B. 1848-8 F.B. 2336-69
COUNTY SURVEYORS SEC. COR. R17W 25 30 36 31 R16W T1S MONUMENT
N0°08'45"E 2377.39
Section Line
N89°53'05"W - (2564.02) per F.B. 1848-8
Section Line
1/4 SECTION CORNER Found County Surveyor Monument marked: See F.B. 1848-13 F.B. 2336-87
COUNTY SURVEYOR 1/4 COR. SEC. 30 SEC. 31 T1S RE 63
N89°49'45"W - 2735.38
616.16
2119.22
Set 1" iron pipe, plug & brass tag marked "L.A.CO.ENGR." flush with surface. F.B. 2336-96, 104
N89°35'40"E 352.59
201.63
150.51
0.38
1031.31
SECTION CORNER Found County Surveyor Monument marked: See F.B. 2659-109, Road Dept. F.B. T-58-1, F.B. 2336-83, 105
COUNTY SURVEYOR T1S R16W 30 29 31 32 RE 2177
CLOSING CORNER Found charred 4"x4" post 8" above surface. This post appears to be one set by C.S. 9237 for Closing Corner & found per C.S. 7915, used for line. Searched for Sandstone Rock, found nothing. F.B. 2336-106
CLOSING CORNER Set 1" iron pipe & brass tag marked: "L.A.CO.ENGR." by intersection on Rancho Line & between 2" iron pipe & Southeast Cor. Sec. 30. The line crosses the 4"x4" stake. F.B. 2336-106
Found 2" iron pipe, wood plug & nail no reference. C.S. 7915 calls for 1"x1" stake. F.B. 2336-106
RANCHO CORNER B.S.M. VII Found 2 1/2" iron pipe with 2"x2" wood plug & R.E. Tag Nº 122. See F.B. 2659-108 F.B. 2336-110
N
S

CSB-2887
A2 OF A2

CSB-2887
A1 OF A2

COUNTY OF LOS ANGELES

MAP OF
SECTIONS 29 & 30, T.1S., R.16W., S.B.M.
SECTIONS 25 & 26, T.1S., R.17W., S.B.M.

COUNTY SURVEYORS MAP NO. B-2887
SCALE:- 1 INCH = 300 FT.

JOB NUMBER 0302.01

JOHN A. LAMBIE - COUNTY ENGINEER
SURVEYED SEPT. 1961 - DEC. 1963

THIS WORK DONE UNDER PROVISIONS OF SECTIONS 27580 TO 27583, GOVERNMENT CODE. REQUIRING THE COUNTY ENGINEER TO PERPETUATE ORIGINAL GOV'T. CORNERS FOUND IN PERISHABLE CONDITION.

BEARINGS ARE BASED ON THE CALIFORNIA COORDINATE SYSTEM ZONE 7. PER SEC. 8809 PUBLIC RESOURCES CODE SEE C.S. 9423

F.B. 2336-69-127, 161-193

FIELD WORK BY .... J. M. UHARRIET
.... L. V. SMITH
OFFICE WORK BY .... R. S. DOWNS
CHECKED BY .... H. E. AUSTIN

IM 89
129-097

Changed north 1/2 Sec. Cor. of Sec. 30
Jan. 1966. G.H.B.

COUNTY SURVEYORS MAP NO. B-2887