





R A N C

SEE F.M. 12010-1



INCOMPLETE
AND/OR
SUBJECT TO CHANGE

F.M. 12010-2
ALL OF A51

From Map F1307 to Maps F1309 & F1310
33 The Newhall Land & Farming Co.
F1309-33
F1310-33
From Map F1307 to Maps F1309 & F1310
50 The Newhall Land & Farming Co.
F1309-50
F1310-50
Continued from Map F1307
5 The Newhall Land & Farming Co.
F1307-5


PAR 1 The Newhall Land & Farming Co.
B7081-34
F1307-34
PAR 5 The Newhall Land & Farming Co.
B7081-36
F1307-36
PAR 6 The Newhall Land & Farming Co.
B7081-36
F1307-36
PAR 10 The Newhall Land & Farming Co.
B7081-28
F1307-28
PAR 11 The Newhall Land & Farming Co.
B7081-28
F1307-28

PAR 1 The Newhall Land & Farming Co.
B7081-34
F1307-34
PAR 5 The Newhall Land & Farming Co.
B7081-36
F1307-36
PAR 6 The Newhall Land & Farming Co.
B7081-36
F1307-36
PAR 10 The Newhall Land & Farming Co.
B7081-28
F1307-28
PAR 11 The Newhall Land & Farming Co.
B7081-28
F1307-28

PAR 1 The Newhall Land & Farming Co.
B7081-34
F1307-34
PAR 5 The Newhall Land & Farming Co.
B7081-36
F1307-36
PAR 6 The Newhall Land & Farming Co.
B7081-36
F1307-36
PAR 10 The Newhall Land & Farming Co.
B7081-28
F1307-28
PAR 11 The Newhall Land & Farming Co.
B7081-28
F1307-28

2-AJ
ot (a.02.M9) 00+eae .pt2

N C H O S A N



Bearings, Distances and Stations of
1963 Freeway Certification are
based on 1963 Geodimeter Survey.

Bearings, Distances and Stations of
1960 Freeway Certification are
based on 1960 Survey.

PAR 1 The Newhall Land & Farming Co.
Slope Error 2.10.69
D.4311-520

B7081 The Newhall Land & Farming Co.
Slope Error 2.27.68
D.4311-522

50.1 The Newhall Land & Farming Co.
Slope Error 2.27.68
D.4311-522

PAR 2 The Newhall Land & Farming Co.
Slope Error 2.18.69
D.4311-522

B7081 The Newhall Land & Farming Co.
Slope Error 2.27.68
D.4311-522

B7081 The Newhall Land & Farming Co.
Slope Error 2.27.68
D.4311-522

PAR 3 The Newhall Land & Farming Co.
Slope Error 2.18.69
D.4311-521

B7081 The Newhall Land & Farming Co.
Slope Error 2.27.68
D.4311-522

B7081 The Newhall Land & Farming Co.
Slope Error 2.27.68
D.4311-522


PAR 4 The Newhall Land & Farming Co.
Slope Error 2.18.69
D.4311-520

B7081 The Newhall Land & Farming Co.
Slope Error 2.27.68
D.4311-522

B7081 The Newhall Land & Farming Co.
Slope Error 2.27.68
D.4311-522

FM 112010-2
A25 OF A51

F.M. 112010-2
A4 OF A5



LA 186
48076
1

LA 186
48076
2

LA 186
48076
3

Parcel 1 Continued on Map F1309
State to Los Angeles County
Rel. 431
Parcel 2 & 3 on Map F1309
Parcel 3 also on Map F1309

State of California &
Socony Mobil Oil Co.
Use Agreement
Entered into 10-28-65

LA 186
48076
4

LA 186
48076
5

LA 186
48076
6

LA 186
48076
7

State of California
& Socony Mobil Oil Co.
Common Use Agmt.
Entered into 10-28-65

LA 186
48076
8

LA 186
48076
9

LA 186
48076
10

LA 186
48076
11


The Newhall Land & Farming Co.
Fee
D 4311-308/580

LA 186
48076
12


LA 186
48076
13

LA 186
48076
14

LA 186
48076
15



FI308



-NOTE-
Line 1 - E. of 100' R/W per OR: 7377-255
Line 2 - E. of 1940 Survey
Line 3 - E. of proposed 160' R/W (1948)
Line 4 - E. of 60' R/W per D: 6055-284
A' Bearings, Distances and Stations are based on 1960 Survey.

378.44
Temp. Ease.
(Constr.)

INCOMPLETE
AND/OR
SUBJECT TO CHANGE

FM 1120110-2
A5
OF
A51

R/W RECORD MAP
NOT TO BE TAKEN
FROM DISTRICT OFFICE
COORDINATES SHOWN ARE FOR INTERNAL
USE OF THE DIVISION OF HIGHWAYS AND
ARE TO BE USED FOR REFERENCE ONLY

STATE OF CALIFORNIA
HIGHWAY TRANSPORTATION AGENCY
DEPARTMENT OF PUBLIC WORKS
DIVISION OF HIGHWAYS

ROAD: 7-LA-5
(Old 7-LA-4-F)

RIGHT OF WAY MAP
1-3/4 Mi. N. of Pico Canyon Rd. (PM50.6N)
to Santa Clara River (PM52.3N)

1" = 249.097'
244.097'

REPRODUCIBLE COPY FILED WITH CO. SURVEYOR