1/4 SECTION CORNER
Nothing found
Located by projection between section corner
Survey of W.H. Abroney, made in 1898, calls for
a redwood post, 3"x3"square, by 3'long, in mound
of rocks, on a side hill facing west for a sec-
tion corner on the east boundary of Township,
between Sections 18 and 19 and on the east bound-
ary of Section 18. (C.S. 9369-I)
Set 2" iron pipe in concrete with brass cap
marked _____. F.B. 85-16
SECTION CORNER
Found by County Surveyor
Survey of W.H.Abroney in 1878, calls for a post
with corner set more than 40 ft. E.
WITNESS CORNER
Survey of W.H.Abroney in 1878, calls for a post
4"square, 3'high, for witness corner to
Section corner, set more than 40 ft. E.
1/4 SECTION CORNER
Found by County Surveyor
Survey of W.H.Abroney in 1878, calls for a post
4"square, 3'high, for witness corner to
1/4 section corner, set more than 40 ft. E.
SECTION CORNER
Found by County Surveyor
Survey of W.H.Abroney in 1878, calls for a post
4"square, 3'high, for witness corner to
Section corner, set more than 40 ft. E.
1/4 SECTION CORNER
Found by County Surveyor
Survey of W.H.Abroney in 1878, calls for a post
4"square, 3'high, for witness corner to
1/4 section corner, set more than 40 ft. E.
SECTION CORNER
Found by County Surveyor
Survey of W.H.Abroney in 1878, calls for a post
4"square, 3'high, for witness corner to
Section corner, set more than 40 ft. E.
1/4 SECTION CORNER
Found original corner stake in mound of rocks, an
Survey of W.H.Abroney in 1878, calls for a
post 4"square, 3'in earth, 1'above stone mound,4
in diameter at base, by 3'in height, for 1/4 section
corner (C.S. 9369-I)
Found by County Surveyors in April, 1926, and accept-
ed for the 1/4 section corner.
Replaced juniper stake with 2" iron pipe set
in concrete with brass cap marked _____.
F.B. 85-16, 30
SECTION CORNER
Found original corner stake in mound of rocks, on
Survey of W.H.Abroney in 1878, calls for a
post 4"square, 3'in earth, 1'above stone mound,4
in diameter at base, by 3'in height, for section
corner (C.S. 9369-I)
Found by County Surveyors in April, 1926, and accept-
ed for the section corner.
Replaced juniper stake with 2" iron pipe set
in concrete with brass cap marked _____.
F.B. 85-16, 30
1/4 SECTION CORNER
Found original corner stake in mound of rocks, on
Survey of W.H.Abroney in 1878, calls for a
post 4"square, 3'in earth, 1'above stone mound,4
in diameter at base, by 3'in height, for 1/4 section
corner (C.S. 9369-I)
Found by County Surveyors in April, 1926, and accept-
ed for the 1/4 section corner.
Replaced juniper stake with 2" iron pipe set
in concrete with brass cap marked _____.
F.B. 85-16, 30
Found by County Surveyor in March, 1928 a
small mound of stone, 3' north of 8"x8"gran-
ite stone. No mose or fungus growth on
north side of rocks in mound. F.B. 245-171
Found by County Surveyor in March, 1928,
a 20"x8" stake, 1 north of 8"x8" granite stone,
2"x2" stake marked "Car Creek Ranch".
F.B. 245-171
Found by County Surveyor in March, 1928
an 8"x8" granite stone, 4"above the surface,
with 4 notches on the east side, and four
notches on the south side. Notches are
flat now. F.B. 245-171
SECTION CORNER
Located by intersection of the lines from the 1/4 corn-
through top of round peak, as shown on the W.H.
Abroney survey of 1878, and line from the south at
record distance (7140') from tip of ridge to south per (S.S.9369)
Survey of W.H.Abroney, made in 1878, calls for a
post 4"square, 3'in earth, 1'above stone mound, 4ft in
diameter at base, by 3'in height for corner to sec-
tions 8, 9, 16 and 17. (C.S. 9369-I)
Set 2" iron pipe in concrete with broken rock mar-
ked _____. F.B. 245-171
1/4 SECTION CORNER
Found old rock mound, with a burned 2"x4" stake nearby.
Survey made by W.H.Abroney in 1878, calls for a post 4"
square, 1'in earth and 1'above stone mound, 4ft in diam-
eter at base, by 3'in height for corner to sections 8, 9,
16 and 17. (C.S. 9369-I)
Found by County Surveyors, in 1926, and accepted for
the 1/4 section corner.
Replaced rock mound with 2" iron pipe set in
concrete with broken rock marked _____.
F.B. 85-16, 30
1/4 SECTION CORNER
Found old rock mound, with a burned 2"x4" stake nearby.
Survey made by W.H.Abroney in 1878, calls for a post 4"
square, 1'in earth and 1'above stone mound, 4ft in diam-
eter at base, by 3'in height for corner to sections 8, 9,
16 and 17. (C.S. 9369-I)
Found by County Surveyors, in 1926, and accepted for
the 1/4 section corner.
Replaced rock mound with 2" iron pipe set in
concrete with broken rock marked _____.
F.B. 85-16, 30
SECTION CORNER
Found old rock mound, with a burned 2"x4" stake nearby.
Survey made by W.H.Abroney in 1878, calls for a post 4"
square, 1'in earth and 1'above stone mound, 4ft in diam-
eter at base, by 3'in height for corner to sections 8, 9,
16 and 17. (C.S. 9369-I)
Found by County Surveyors, in 1926, and accepted for
the section corner.
Replaced rock mound with a