NORTHERLY BOUNDARY RANCHO LOS AMIGOS

S 57°57'20"E

330.00

100.00

310.00

200.22

PM #49 Set 2"x2" stake F.B. 153-16

PM #48 Set 2"x2" stake F.B. 153-15

PM #47 Set 2"x2" stake F.B. 153-16

PM #46 Set 2"x2" stake F.B. 153-15

Found County Surveyors monument with brass cap per F.M. 100-33, F.B. 153-8

Set Nail in stake Mark F.B. 153-15

ANGLE POINT Found nail in blaze in 12" Cott. Root Dead F.B. 141-7, F.B. 153-15

PM #45 Set 3/4" pin convenient F.B. 153-15

Pasture

Pasture

Pasture

8" Oak 33° E 4.0 ft.

Irrigation Valve

Irrigation Valve

Irrigation Valve

B.M. El. 103.51
Chisel in top of S' below surface
Ties: S. 67°-42' E. 113.53-17

Found 3/4" iron pipe & tag surface per F.B. 153-17

Found 1" iron pipe, Plug and Tack, per F.B. 153-17

PM 56
Set 2"x2" stake
F.B. 153-17

P.I. El. 102.21

P.I. El. 99.00

Transit line of 466.91

P.I. El. 102.98

P.I. El. 99.50

PM 54
Set 2"x2" stake
8" below surface
F.B. 153-17

PM 53
Set 2"x2" stake
F.B. 153-16

PM 52
Set 2"x2" stake
F.B. 153-16

P.I. El. 103.00

PM 51
Set 2"x2" stake 8" below surface F.B. 153-16

PM 50
Set 2"x2" stake
F.B. 153-16

PM 49
Set 2"x2" stake
F.B. 153-16

C.M. 11
Set 2"x2" stake 12" in low surface, F.B. 153-42

S. 57°-57'-20" E.

400.00

300.00

380.00

NORTHERLY BOUNDARY RANCHO LOS AMIGOS

RANCHO LOS AMIGOS WESTERLY BOUNDARY

345.10

Bank & Waste Ditch

Bank & Waste Ditch, Dry Bed

Top of Bank

Toe of Slope

Cultivated Land

Pasture

Cultivated Land

C.M. 8
Set 2"x2" stake
F.B. 153-42

C.M. 9
Set 2"x2" stake
F.B. 153-42

C.M. 10
Set 2"x2" stake
F.B. 153-42

N. 0°-16'-10" E.

300.00

Irrigation Ditch

Irrigation Ditch

Irrigation Ditch